Appendix D

Data Management Plan for Field and Nonchemical Data from the Operable Unit 3-13, Group 4 and Group 5 Well Installation and Monitoring Projects

> DOE/ID-10768 Revision 0

[The document that is the subject of this appendix was provided as an attachment to the original deliverable.]

To view this Appendix, please see specific "Stand Alone" document number

[Editor's note: Appendix E, Cost Estimate, does not include a flysheet.]

Bechtel BWXT Idaho, LLC

COST ESTIMATE SUPPORT DATA RECAPITULATION

Project Title: WAG 3 Group 5 SRPA Wells

Estimator: J. C. Grenz

Date: October 23, 2000

Estimate Type: Planning File: 2975-A

Approved By:

I. SCOPE OF WORK: Brief description of the proposed project.

The scope of this project is to deepen four existing wells, Drill one new well, and to monitor existing INTEC wells.

- A. Deepen four existing USGS wells by core drilling approximately 125 feet deeper.
- B. Test the deepened wells and then backfill them back to their current depth..
- C. Drill one new deep well.
- D. Monitor 47 wells once and 20 wells once each year.
- E. Construct a temporary evaporation tank and haul the water to it
- II. BASIS OF THE ESTIMATE: Drawings, Design Report, Engineers Notes and/or other documentation upon which the estimate is originated.

Brief scope of work from geologists.

- III. ASSUMPTIONS: Conditions statements accepted or supposed true without proof of demonstration. An assumption has a direct impact on total estimated cost.
 - A. Work to be performed in 2001 and beyond.
 - B. Work will be performed by a contractor familiar with drilling at the INEEL.
- IV. CONTINGENCY GUIDELINE IMPLEMENTATION: The percentage used for contingency as determined by the contingency allowance guidelines can be altered to reflect the type of construction and conditions that may impact the total estimated cost.

A 25% contingency, which includes costs for management reserve, has been included in the estimate. This is within the acceptable range for an estimate at this stage of development. Lack of written scope was the primary driver to arrive at this amount of contingency.

COST ESTIMATE SUPPORT DATA RECAPITULATION

- Continued -

Project Title: WAG 3 Group 5 SRPA Wells

2975-A

File:

Page 2

V. OTHER COMMENTS/CONCERNS SPECIFIC TO THE ESTIMATE

- A. Costs on the detailed cost sheets are direct costs and do not include overhead, profit or escalation for the drilling sub-contractor.
- B. Due to the minimal detail and scope definition, this estimate is considered a "Planning" estimate and is not intended to be used to establish a cost baseline.

E-2

Project Name: WAG 3 Group 5 Wells Project Location: INTEC Estimate Number:2975-A	5 5 Wells on: NYEC ber 2975-A	Project Summary Report	eport	Cient: Prepared By: Estimate Type	Client: C. J. Roberts Prepared By: J. C. Grenz Estimate Type: Planning	
LEVEL	REMEDIAL ACTION	Estimate Subtotal \$860,517	Escalation \$863	Contingency \$215,345	Contingency % 25.00%	TOTAL \$1,076,725
60280	-Yr 2 Sampling (47 wells)	\$88,673	%	\$22,168	25.00%	\$110,842
50280.01		\$10,899	9	\$2,725	25.00%	\$13,624
50280.02	Analysis & Validation (50290/61101)	\$11,114	0\$	\$19,444	25.00%	\$97,218
50350	-Yr 2 Sampling (20 wells)	\$53,457	9	\$13,364	25.00%	\$66,821
50250.01		\$4,638	2	\$1,160	26.00%	\$5,798
50350.02		\$48,819	9	\$12,205	25.00%	\$61,024
51095	-Yr 2 Micropurge (20 wells)	\$145,069	0\$	\$36,267	25.00%	\$181,336
51095.01	Micropurge	\$91,612	8	\$22,903	25.00%	\$114,515
51095.02		\$4,638	9	\$1,160	25.00%	\$5,798
51095.03		548,819	2	\$12,205	25.00%	\$61,024
50430	-Yr 3 Sampling (20 wells)	\$53,457	9	\$13,364	25.00%	\$66,821
50430.01		\$4,638	2	\$1,160	25.00%	\$5,798
50430		\$48,819	8	\$12,206	25.00%	\$61,024
20500	-Yr 4 Sampling (20 wells)	\$53,457	0 \$	\$13,364	25.00%	\$66,821
50500.01		\$4,638	8	\$1,160	25.00%	\$5,798
50500.01		\$48,819	2	\$12,205	25.00%	\$61,024
50560	Yr 5 Sampling (20 wells)	\$53,457	<u> </u>	\$13,364	25.00%	\$66,821
50560.01		£,63	0\$	\$1,160	25.00%	\$5,798
50560.02	Analysis & Validation (60570/50680)	\$48,819	0\$	\$12,205	25.00%	\$61,024
50620 INEEL	Yr 6 Sampling (20 wells)	\$63,467	0\$	\$13,364	25.00%	\$66,821
10/24/2000	15:14:19 Suc	Success Estimating and Cost Management System	int System		Page No.	-

10/24/2000 15:14:19

INEEL

C. J. Roberts Prepared By: J. C. Grenz Estimate Type: Planning	Contingency Contingency % 25.00% 25.00%	\$12,209	\$2,081 25.00%	\$6,938 \$8,584 25.00%		\$973 25.00% e4 145 25.00%	\$125 25.00%		\$21,406 25.00%	\$3,542 \$18.972 25.00%	\$6,020	\$2,633 25.00%	\$3,387 25,00%	\$5,834 25.00% \$6,547 25.00%	\$571 25.00%	\$3,753 23.00 x
ť	Escalation Co	2	200	0\$	2 2	%	3.	3.	9	.	\$863	\$120	\$154	\$265	\$28	\$
Project Summary Report	Estimate Subtotal	\$48,819	\$359,490 \$8,324	\$27,763	\$26,334	088,54	\$5,258	6675	\$85,623	\$13,369	\$75,024	\$23,805 \$10,410	\$13,384	\$23,071	\$25,888 \$2,260	\$15,013
	∪ ₹			edund lind	Advance 4 Wells	Il New Well	Haul Water	Quality Assurance	Monitor New Well , 4 Advanced Wells, & 3 Existing Wells	Analysis & Validation of 8 Wells	Bore Hole Logging of 8 Wells	Engineering and Technical Support	-	B CONSTRUCTION MANAGEMENT	ER 1221.04.08.1 ——CONSTRUCTION SUPERVISION & ENGINEERINGE PROPERTIONS/CONDUCT OF MAINTENANCE	98RADIATION CONTROL NON-Org G&A and PIF
e Parent	Project Society 5 Wells WAG 3 Group 5 Wells Project Location: INTEC Estimate Number 2975-A	LEVEL 50620.01	50620.02	-	50730.02	50730.03	60750.06	50750.10	50730.20	E4 80730.21		50750.11	ER 1221.04.01.1	ER 1221.04.01.2 ER 1221.04.08	ER 1221.04.08.1	ER 1221.04.09 GAPIF

\$16,711 \$94,858 \$30,098 \$13,163 \$16,935 \$61,903 \$29,771 \$32,733

TOTAL \$6,736 \$61,024 \$10,405 \$32,918 \$141,768 \$4,863 \$6,673

			1	č		
oroject name: WAG 3 Group 5 Wells Project Location: INTEC Estimate Number:2975-A	5 Wells nr: INTEC ber:2975-A	roject Summary Keport	L	Chent: Prepared Estimate	C. J. Roberts Prepared By: J. C. Grenz Estimate Type: Planning	
LEVEL		Estimate Subtotal	Escalation	Contingency	Contingency %	TOTAL
rotal WAG	otal WAG 3 Group 5 Wells	\$875,530	\$863	\$219,098	25.00%	\$1,095,491
				1		
INEEL						
10/24/2000	15:14:19 Succe	Success Estimating and Cost Management System	rt System		Page No.	es O

10/24/2000

Project Name: WAG 3 Group 3 Wells Project Location: INTEC Estimate Number: 2973-A	S	CONSTRUCTION DETAIL ITEM REPORT	. ITEM REPO	Σ.	Client: Prepared Estimate	Client: C. J. Roberts Prepared By: J. C. Grenz Estimate Type: Planning	berts enz g
LEVEL Org/Subcontractor - 50280.01 Monitor 47 Wells (50280) Take Samples	U.C. per ea 47.00	Hrs Crew/Rate 10 715 470 \$21.19	211.9	Const Eqp	Mati 20 \$940	S/C	Other
Subtotal Sales Tax INEEL ORG Labox/Subcontractor Overheads			\$9,958 \$0 \$0	0 0 0 0 0	\$60 \$0 \$0	8 8 8	2 2 2
Subtocial Estimate Escalation Controgency			\$0	25.05	\$0 \$23\$	9,9	3 3 3
-Total 50280.01 Monitor 47 Wells (50280)		470	\$12,449	S.	\$1,175	a	2
- 60280.02 Analysis & Validation (6028061101) U.C. per is 1.00 0 0 Samplev/aiadate Nemo: Water Samples: Gross Beta, Tritium, Uranium, Meptunium, Plutonium, Americum, Iodine, Strontium, Gross Alpha/Beta, Anlons, Metals, Rad Valadetion, and I&MCA Validation	U.C. per ls 1.00 nunium, Plutonium, Americium, lo	0.2 0 Odine, Strontium, Gross Alpha/Betz	0 \$0 Anions, Metais, Ra	0 \$0 rd Valadation, and	0 \$0 I&MCA Validation	\$17.77 \$17.77	° °
Subtotal			2	0\$	8	\$77,774	9

231.9 \$10,899 \$10,899 \$0 \$0 \$10,899 \$10,899 \$2,725 \$13,624

\$77.774 \$77,778

Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					3 G G	3 3 S	888	\$77,774 \$0 \$0	222	\$77,774 \$0 \$0
Subtoral Estimate Escalation Contingency					\$ \$	S S	25 25	\$19,444	2.2	\$77,774
-Total 50280.02 Analysis & Validation (50290/51101)	-		•		0\$	æ	2	\$97,218	3	\$97,218
	U.C. per ea	20.00	10 200 200	T15 \$21.19	211.9 \$4,238	0 0	20 20 20	a 9	° 5	231.9 \$4 ,638
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$4,238 \$0 \$0	2 2 2	2 2 3 3 3 3 3 3	2 S S	888	\$4,638 \$0
Subtodal Estimate Escalation Contingency					\$0	22	\$ 100 0 \$ 100	9. S.	9.9	\$1,160
Total 50250.01 Monitor 20 Wells (50350)			200		\$5,298	S	\$600	2	25	\$5,798
Santievaled to Wallet Simple Coss Beta Triffum Unantium Plutonium Americium Indian Create Antonium Create	U.C. per Is	1.00	0.2	:	0 0	° <u>°</u>	۰ چ	48819 \$48,819	° %	48819 \$48,819

Project Name: WAG 3 Group 5 Wells Project Location: INTEC Estimate Number:2975-A		CONST	RUCTI	CONSTRUCTION DETAIL ITEM REPORT	ITEM REI	PORT	Client: Prepare Estimat	Client C. J. Roberts Prepared By: J. C. Grenz Estimate Type: Planning	oberts renz ng	
LEVEL Org/Subcontractor 60350.02 Analysis & Validation (60360/80370)	ATA T	E E		Crew/Rate	Labor	Const Eqp	Mati	S/C	Other	TOTAL
Subtotal Sales Tax INEEL ORG Labor/Subconfractor Overheads					8 2 2	S S S	888	\$48,819 \$0 \$0	222	\$48,819
Subtotal Estimate Escalation Confingency					0\$ \$\$	0\$	0\$	\$12,205	0,05	\$48,819 \$0 \$12,205
Total 50350.02 Analysis & Validation (50360/50370)			0		3	0\$	9	\$61,024	s	\$61,024
51095.01 Micropurge Mamo: 10 hours per well for boom truck and 3 men. U.C. per hr Boom Truck Memo: Pull 20 pumps, install MP pumps, pull MP pumps, and relinstall regular pumps	U.C. per hr 200.00 stall regular pumps	8	•		0 0	62.5 \$12,500	° °	o <u>o</u>	o 0 5	62.5 \$12,500
DRILL U.C. I Boom Truck Labor	U.C. per hr 600.00		- 8	CN-LABR \$30.09	30.09	° 9	° <u>0</u>	° <u>0</u>	° 9	30.08 \$18,054
DRILL U.C. I Purchase Pumps & Contris	U.C. per ea 10.00	8	0		° 0 5	o 9	3670 \$36,700	o s	o og	3670 \$36,700
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$18,054 \$0 \$6,539	\$12,500 \$0 \$4,527	\$36,700 \$0 \$13,292	3 S S	888	\$67,254 \$0 \$24,358
Subtotal Estimate Escalation Contingency	-			•	\$0 \$6,148	\$0 \$4,257	\$12,498	88	88	\$91,612 \$0 \$22,903
-Total 51095.01 Micropurge			909		\$30,741	\$21,284	\$62,490	2	æ	\$114,515
- 51095.02 Micropurge Sampling 20 Wells (51095) Take Samples	U.C. per ea 20.00		10 T	T15 \$21.19	211.9 \$4,238	0 05	20 2400	0 0	° 9	231.9 \$4,638
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$0 \$0 \$0	222	24 03 03 03 03	05 05 05 05	25.25	\$4,638 \$0 \$0
Subfotal Estimate Escalation Contingency					\$1,060	95 S\$	\$0 \$100	0\$	0\$	\$4,638 \$0 \$1,180
—Total \$1095.02 Micropurge Sampling 20 Wells (51095)			200		\$5,298	0\$	009\$	Q.	0 \$	\$5,798

e			
ì	3		
į	٠		
i	•	٠	
,	,		
١	2		
i	ì		

Page No.

E
ጀ
ž
Ě
8
Š
ž
8
ç
ş
Ę
Ě
Esti
888
Šveč
-,

LEVEL Org/Subcontractor						Prepare Estimate	Estimate Type: Planning	ğı Bi	
	OTY © Valadation (51096/51100)	H.	Crew/Rate	Labor	Const Eqp	Mati	S/C	Other	TOTAL
Sample/Valadate Memo: Water Samples: Gross Beta, Tritlum, L	U.C. per Is 0.2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0.2 1.00 0 aricium, Iodine, Strontii	2 0 tium, Gross Alpha/Beta	0 50 , Anions, Metais	n \$0 Rad Valadation, a	0 \$0 Ind I&MCA Validation	48819 \$48,819 n	o <u>o</u>	48819 \$48,819
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads	8			888	8 8 8	888	\$48,819 \$0 \$0	222	\$48,819 \$0 \$0
Subtotal Estimate Escalation Contingency				88	25.05	89	\$0 \$12,205	88	\$48,819 \$0 \$12,205
Total 51095.03 Micropurge Sample Analys (51096/51100)	ysis & Valadation			2	S.	3	\$61,024	S.	\$61,024
50430.01 Monitor 20 Wells (40430) Take Samples	U.C. per ea	20.00 200	0 T15 0 \$21.19	211.9 \$4,238	° 0 5	20 4400	o <u>o</u>	° 0¢	231.9 \$4,638
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads	\$1			\$4,238 \$0 \$0	0,00	2400 30 30 30 30	S S S	\$ 8 B	\$4,638 \$0 \$0
Subtocial Estimate Escalation Contingency	-			\$0 \$1,060	9 9	\$100	0 S	88	\$4,638 \$0 \$1,160
Total 50430.01 Monitor 20 Wells (40430)		200		\$5,298	2.	\$500	S	Q.	\$5,798
<u>50430 Analysis & Validation (50440/50456)</u> SampleAvaladate Memo: Water Samples: Gross Beta, Tritium, Urs	U.C. per ls 0.2 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	0.2 1.00 0 aricium, lodine, Stronti	2 0 tium, Gross Alpha/Beta	o \$0 , Anions, Metala	0 \$0 , Rad Valadation, a	0 \$0 and I&MCA Validation	48819 \$48,819	o g	48819 \$48,819
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads	_			03 62 62	222	888	\$48,819 \$0 \$0	333	\$48,819 \$0 \$0
Subtotal Estimata Escalation Contingency				8 3	0,0	<u>0</u> , 0,	\$0 \$12,205	000	\$48,819 \$0 \$12,205
	(150450)		0	2	%	0\$	\$61,024	0\$	\$61,024
Take Samples	U.C. per ea	20.00 200	5 T15 \$21.19	211.9 \$4,238	o 9	20 \$400	° 0	° 00	231.9

CONSTRUCTION DETAIL ITEM REPORT Project Name:

C. J. Roberts Client:

Project Location: INTEC Estimate Number: 2975-A						CSULIBRIC	Estimate Type: Framming	<u>D</u>	
LEVEL Org/Subcontractor 50500.01 Monitor 20 Wells (50500)	ΔŢΔ	EH	s Crew/Rate	Labor	Const Eqp	Mati	S/C	Other	TOTAL
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads				\$4,238 \$0 \$0	888	25 08 08 08	222	888	\$4,638 \$0 \$0
Subtotal Estimate Escalation Contingency				\$1,080	22	\$100	0, 0,	33	\$4,638 \$0 \$1,160
Total 60500.01 Monitor 20 Wells (50500)			200	\$5,298	93	\$500	9 \$	2	\$5,798
Sample/Valed Standard Const. Const. More C	U.C. per is	1.00 1.00 1.00 1.00	0.2	0	0 \$0	0 \$	48819 \$48,819	۰ 9	48819 \$48,819
Subtotal Substantia Su				888	222	222	\$48,819 \$0 \$0	888	\$48,819 \$0 \$0
Subtotal Estimate Escalation Confingency				0,0	88	0,0	\$0	22	\$48,819 \$0 \$12,205
-Total 50500.01 Analysis & Validation (50510/50520)			0	S	3	8	\$61,024	2	\$61,024
<u>60860.01 Monitor 20 Wells (606560)</u> Take Samples	U.C. pereia	20.00	10 T15 200 \$21.19	211.9 \$4,238	o 0 3	20 \$400	o 9	o ç	231.9 \$4,638
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads				\$4,238 \$0 \$0	222	\$400	\$ \$ \$ \$	888	\$4,638 \$0 \$0
Subtoral Estimata Escalation Contingency				\$1,080	2.2	\$ 100	88	88	\$4,638 \$0 \$1,160
Total 50560.01 Monitor 20 Wells (505560)			200	\$5,298	0\$	\$500	\$	O.	\$5,798
50560.02 Analysis & Validation (50570/50580). SampleValedate	U.C. per is	97	0.2 0	0 0	0 0	0 0	48819	0 9	48819 548 819

\$48,819 \$0 \$12,205 \$61,024

62.5 \$2,500

۰ <u>چ</u>

o 8

° 0

62.5 \$2,500

40.00

--- 60730.01 Pull Pumps
Memo: 10 hours per well for boom truck and 3 men.
U.C. per hr

Boom Truck Memo: Set packers for each zone and pump samples.

\$48,819 \$0

48819 \$48,819

Project Name: WAG 3 Group 5 Wells Project Location: INTEC Estimate Number:2975-A		CONS	TRUC.	CONSTRUCTION DETAIL ITEM REPORT	ITEM REF	ORT	Client: Prepared By: Estimate Type	Client: C. J. Roberts Prepared By: J. C. Granz Estimate Type: Planning	berts enz ig
LEVEL Org/Subcontractor 60850.02 Analysis & Validation (90570/90580)	QTA	-1		Crew/Rate	Labor	Const Eqp	Mati	S/C	Other
Subicial Sales Tax INEEL ORG Labor/Subcontractor Overheads					888	888	888	\$48,819 \$0 \$0	222
Subotal Estimate Escation Contingency					0 S	<u>0</u> , 0,	\$ \$	\$0 \$12,205	9 S
Total 50560.02 Analysis & Validation (50570/50580)			•		\$	0 \$	\$	\$61,024	93
50620.01 Monitor 20 Wells (50620) Take Samples	U.C. per ea	20.00	10 200	T15 \$21.19	211.9 \$4,238	o o	\$ 50 \$400	000	o g
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					7, 20,000 20,000	2 2 2	3000	222	333
Subtotal Estimate Escalation Contingency					\$0	<u>0</u> 0	\$0 \$100	0 G	00 00 00 00
Total 50620.01 Monitor 20 Wells (50620)			8		\$5,298	3	\$500	2	9
	U.C. per is nium, Plutonium, Amv	1.00 nicium, lodine,	0.2 0 Strontium	1, Gross Alpha/Beta,	0 \$0 Anions, Metals	0 \$0 s, Rad Valadation, and	0 \$0 d I&MCA Validation	48819 \$48,819	° °\$
Subidal Sales Tax INEEL ORG Labor/Subcontractor Overheads					0 0 0 0 0 0 0 0	05.05	03 03 03 03	\$48,819 \$0 \$0	05 05
Subtotal Estimate Escalation Conlingency		:			\$0	0\$ \$	0\$	\$0 \$12,205	0 \$
Total 50620.02 Analysis & Validation (50630/5640)	-		0		O \$	0\$	S	\$61,024	0\$

7,638 07,03

231.9 \$4,638

\$4,638 \$0 \$1,160 \$5,788

\$48,819 \$0 \$0

\$48,819 \$0 \$12,205 \$61,024

10/24/2000

	Project Name: WAG 3 Group 5 Wells Project Location: INTEC		Ö	ISTRUC	CONSTRUCTION DETAIL ITEM REPORT	. ITEM REI	PORT	Client: Prepare Estimate	Client: C. J. Roberts Prepared By: J. C. Grenz Estimate Type: Planning	oberts renz	
	Estimate Number: 2975-A									•	
	LEVEL Org/Subcontractor - 50730.03 Sample and Replace Pumps	QTV	٦	I S	Crew/Rate	Labor	Const Eqp	Mati	S/C	Otther	TOTAL
	Memo: Sample 4 wells DRILL	U.C. per lb				0	0	0.1	0	0	0.1
	Bentonite		10,000.00	0		9	0	\$1,000	9	S	\$1,000
	Subtotal					\$10,832	\$7,500	\$1,000	9.5	05	\$19,332
	Sales Tax INEEL ORG Lebor/Subcontractor Overheads					\$3,923	\$0 \$2,718	\$0 \$362	& &	S S	\$00'2\$
	Subtotal Estimate Escalation Confinence					0\$ \$3.689	\$0 \$2.554	\$0\$	25.55	0 S	\$26,334 \$0 \$6.584
	Total 50730.03 Sample and Replace Pumps			360		\$18,445	\$12,770	\$1,703	9	2	\$32,918
	50730.04 Drill New Well Memo: New deep wal! DRILL	U.C. per if				\$	2	۰	0	۰	11
	Driff Well		570.00	0		\$23,940	\$41,040	8	9	80	\$64,980
E-12	DRILL Install Casing(5,10,14,18) Memo: Cassings are GFE	U.C. per If	1,110.00	•		\$3,330	\$5,550 55,050	° 0 5	o g,	o g	\$8,880
	DRILL Grout and Gravel	U.C. per d	400.00	0		8.3 \$3,320	14.2 \$5,680	\$	° 9	° 9	23.5 \$9,400
	Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$30,590 \$0 \$11,079	\$52,270 \$0 \$18,931	\$400 \$0 \$145	333	g 8 8	\$83,260 \$0 \$30,155
	Subtotal Estimate Escalation Contingency					\$10,417	\$0 \$17,800	\$0	0.0	88	\$113,415 \$0 \$28,354
	-Total 80730.04 Drill New Well			0		\$52,086	\$89,001	\$681	3	2	\$141,768
	<u>\$0750.06</u> Haul Water DRILL Haul Water to SSSTF (175K gal)	U.C. per hr	80.00	± 09	CN-TRHV \$32.60	32.6 \$1,958	15	o g	o g	o <u>o</u>	47.6 \$2,856

Project Name: WAG 3 Group 5 Wells Project Location: INTEC Estimate Number: 2975-A		CONS	TRUC	CONSTRUCTION DETAIL ITEM REPORT	ITEM REF	ORT	Client: Prepare Estimat	Client: C. J. Roberts Prepared By: J. C. Granz Estimate Type: Planning	oberts enz ig	
LEVEL Org/Subcontractor	QTY	-1	5 E	Crew/Rate	Labor	Const Eqp	Mati	S/C	Other	TOTAL
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$1,956 \$0 \$708	\$900 \$0 \$326	9 8 8	00 00 00 00	222	\$2,856 \$0 \$1,034
Subtotal Estimate Escalation Contingency					0 \$ 999 \$	\$308	22	0.5	S S	\$3,890 \$0 \$973
-Total 50750.06 Haul Water			99		\$3,331	\$1,532	0\$	æ	s,	\$4,863
— 60760.10 Quality Assurance 00201000 7260 Inspection and Overview	U.C. per WK	6.00	6 9	T12 \$25.01	250.1 \$1,501	° 0,	0 0	0 0	o g	250.1 \$1,501
00203000 7260 Vendor Data Review and Field Problems	U.C. per Wk	6.00	4 5	T12 \$25.01	\$0.02 \$300	o <u>o</u>	° 3	° 6	o 0	50.02 \$300
00205000 7260 Inspection Plan Preparation	U.C. per Ea	1.00	88	T12 \$25.01	\$00.2 \$500	° 0	္ င္အ	0 0	o 0 5	\$00.2 \$500
7380 C Quality Assurance Supervision @ 10%	U.C. per Hr	92.00	0.1	203 \$52.32	5.232 \$481	0 05	့	o 9	0 05	5.232 \$481
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$2,782 \$0 \$2,478	000	2 2 2	2000	0 0 0	\$2,782 \$0 \$2,476
Subtoral Estimate Escalation Contingency					\$1,315	9	908	<u>\$</u>	3 S	\$5,258 \$0 \$1,315
Total 50750.10 Quality Assurance			ē		\$6,673	9	3	9	æ	\$6,573
50730.20 Monitor New Well , 4 Advanced Wells, 6.3 Existing Wells Take Samples	3 Existing Wells U.C. per ea	80.00	0.2	T15 \$21.19	4.238 \$339	° <u>°</u>	\$160	0 0\$	0 05	6.238 \$499
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$338 \$0 \$0	0.00	\$160 \$0 \$0	222	999	\$489 \$0 \$0
Subtotal Estimate Escalation Contingency					\$0 \$85	0 \$	\$20	0 0s	05 55 55	\$488 \$0 \$125
Total 60730.20 Monitor New Well , 4 Advanced Wells, 8.3 Existing Wells	6, 4.3		16		\$454	Q \$	\$200	0\$	0 \$	\$624

Project Name:	CONSTRUCTION DETAIL ITEM REPORT	Client:	Client: C. J. Roberts
WAG 3 Group 5 Wells		Prepared By:	J. C. Grenz
Project Location: INTEC		Estimate Typ	Estimate Type: Planning
Estimate Number: 2975-A		•	•

	LEVEL Org/Subcontractor	Scontractor	ΔŢ		۲ ع	Crew/Rate	Labor	Const Eqp	Mati	S/C	Other	TOTAL
	Sample/Valadate Memo: Water Samples: Gree Beta Trittim	ion of orena da Tritim Hranium Mentinium	U.C. per is	1.00 antrium India	0.2 O	Gross Alpha Gata	So So Material	U.C. per ls 0.2 0 0 0 0 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1	0 \$0 XACA Validation	85623 \$85,623	° 3	85623 \$85,623
	Sublotal Sales Tax						8 8	0\$	0\$	\$65,623	8.8	\$85,623
	INEEL ORG Labor/Subcontractor Overheads Subtotal Estimate Escalation	or Overheads					8 8	S S	9 9	S S	S S	\$85,623
	Contingency Total 50730.21 Analysis & Validation of	lidation of 8 Wells			٥		S S	3 3	<u>s</u>	\$21,406	o s	\$21,406
E-1	50730.22 Bore Hole Logging of 8 Wells DRILL Boom Truck Memo: Set packers for each zone and pump	of 8 Weils a and pump samples.	U.C. per hr	80.00	0		o 00	62.5 \$5,000	o 0	o g	° 9	62.5 \$5,000
4	DRILL Boom Truck Labor		U.C. per hr	160.00	180	CN-LABR \$30.09	30.08 \$4,614	0 05	° 9	° g	0 05	30.09 \$4,814
	Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads	or Overheads					\$1.84 \$0 \$1.74\$	\$5,000 \$0 \$1,811	888	888	888	\$9,814 \$0 \$3,555
	Subtotal Estimate Escalation Contingency						\$0 \$1,640	\$0 \$1,703	0\$ 0\$	9 S	9,9	\$13,369 \$0 \$3,342
	Total 50730.22 Bore Hole Logging of 8 Wells	ging of 8 Wells			160		\$8,198	\$8,514	2	2	8	\$16,711
		STRATION	U.C. per Wik	6.D0	20 120	E30 \$35.80	718	o <u>g</u>	0,0	o g	o g	716 \$4,296

ER 1221.04.01.1 PM ADMINISTRATION Project Management - Management Support - 10% Of P.M. Total	U.C. per Hr	120.00	12	Z04 \$48.29	4.829 \$591	
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$4,887 \$0 \$5,523	İ
Subtotal Estimate Escalation Contingency					\$120 \$2,633	ļ
-Total ER 1221.04.01.1 PM ADMINISTRATION			Ē		\$13,163	l
ER 1221.04.01.2 PM - CONDUCT OF OPERATIONS/CONDUCT OF MAINTENANCE 6210 Assemble Planning Team 1.00	NDUCT OF MAINTE U.C. per Lot	1.00	44	E30 \$35.80	1432 \$1,432	
6210 Initiate Work Control Form (WCF)	U.C. per Ea	1.00	no no	E30 \$35.80	179 \$179	
6210 Update WCF (1 Hour / Day)	U.C. per Wk	6.00	30.5	E30 \$35.80	179	
6210 Initiate Hazards Analysis Process	U.C. per Lot	1.00	44	E30 \$35.80	1432 \$1,432	
6210 Prepare Supporting Project Documents	U.C. per Lot	1.00	8 8	E30 \$35.80	1074 \$1,074	
6210 Post-Job Review	U.C. per Ea	1.00	55	E30 \$35.80	358 \$358	
6210 PM Management Support - 10% Of Total	U.C. per Hr	150.00	1.0	204 \$49.29	4.629	
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$8,288 \$0 \$7,106	
Subrotal Estimate Escalation Contingency					\$154	
—TOM ER 1221.04.01.2 PM - CONDUCT OF OPERATIONS/CONDUCT OF MAINTENANCE	CONDUCT OF		170		\$16,935	l
ER 1221.04.08.1 CONSTRUCTION SUPERVISION & ENGINEERING 00400100	GINEERING U.C. per Wk	6 .00	00 00	E30 \$35.80	358 · \$2,148	

\$6,288 \$7,106 \$13,394 \$154 \$3,387

88 8

ន

20

2 2 2 2

2 2 2 2

0 0 0 0

2 2 2

S 2 2

S S S

358 \$2,148

၀ ဇ္တ

၀ ဋ္ဌ

o g

o 🔉

5

Page No.

Success Estimating and Cost Management System

4.929 \$739

ဝဋ္ဌ

o 8 ۰ چ ° 😭

00,00,00

\$10,410 \$120 \$2,633 \$13,163

2 2

88

88

2 2 8

8

8

다. C Initiate Work Control Form (WCF)

1432 \$1,432 179 \$179 179 \$1,074 1432 \$1,432 1074 \$1,074

o **9** ° % 0 0 o 8 **0** 0 ၀ မှ

o g

o 8

o 😭

000 000 000

o 🔉

\$4,887 \$0 \$5,523

G G G

2 2 S

S 2 2

8 8 8

TOTAL

Other

S/C

Mat

Const Eqp

Labor

Crew/Rate

흔

ΔŢ U.C. per Hr

LEVEL Org/Subcontractor
ER 1221.04.01.1 PM ADMINISTRATION
6210

WAG 3 Group 5 Wells Project Location: INTEC Estimate Number: 2975-A

Project Name:

Client: C. J. Roberts
Prepared By: J. C. Grenz
Estimate Type: Planning

CONSTRUCTION DETAIL ITEM REPORT

၀ ဇ္တ

၀ ဋ္ဌ

° 😭

۰ 🕽

10/24/2000

6340 Prepare Supporting Project Documents	U.C. per Lot	1.00	22 22	25 E30 25 \$35.80	895 \$895	o 0 5	° 9	° <u>G</u>	~ g
6340 Develop Work Order	U.C. per Lot	1.00	4 4	E30 \$35.80	1432 \$1,432	o 0 5	o 0 5	° <u>g</u>	o <u>g</u>
6340 Approve Work Orders - Subject Matter Expert (SME) (5 Hours / SME)	U.C. per SME	1.00	10 10	5 E30 5 \$35.80	179 \$179	0 05	o og	0 05	° 05
6340 Approve Work Orders - CM	U.C. per Lot	1.00	10 10	5 E30 6 \$35.80	179 \$179	0 0\$	o <u>o</u>	° %	၀ င္အ
10/24/2000	ร	iccess Estima	ting a	Success Estimating and Cost Management System	ent System			G.	Page No.

F

E-16

-- Total ER 1221.04.08.1 CONSTRUCTION SUPERVISION & ENGINEERING

Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads

Subtotal Estimate

00401400 8340 Pool Account (Direct Hours @ \$24 Per Hour)

00400500 Quality

\$11,200 \$0 \$11,672

222

222

S 2 2 3

222

\$11,200 \$0 \$11,872

CN-CMOTHE \$11.36

- 8

U.C. per Hour

\$35.80

71.6 \$430 71.6 \$430

00,00,00,00

00, 00, 00, 70, 00,

71.6 \$430 71.5

\$35.80

E30 E30

2 5 2 2

U.C. per Wk U.C. per Wk

U.C. per WK

544.4

P21 \$27.22 E30 \$35.80

8 2

8.00 6.00 6.00

800

LEVEL Org/Subcontractor QTY

— ER 1221.04.08.1 CONSTRUCTION SUPERVISION & ENGINEERING
00400200 6340 U.C. per WK

WAG 3 Group 5 Wells Project Location: INTEC Estimate Number: 2975-A

Project Name:

2300 6340 6340

Subcontract Admin

00400400 ES&H

Construction Engineer

TOTAL

S/C

Mat

Const Eqp

Crew/Rate

Client: C. J. Roberts
Prepared By: J. C. Granz
Estimate Type: Planning

CONSTRUCTION DETAIL ITEM REPORT

11.36

\$23,071 \$265 \$5,834 \$29,171

88 8

ន្ល

3 2 B

ន្ទន ន

\$285 \$5,834

2

358 \$358 1432 \$1,432 716 \$716

o 0

o 🔉

358 \$358 1432 \$1,432

\$35.80 \$35.80

6 6

--- ER 1221.04.08.2 CM - CONDUCT OF OPERATIONS/CONDUCT OF MAINTENANCE 8340
U.C. per Lol 100

1

E30

2 2 88

> 8 8 6.00

U.C. per Lot U.C. per Lot U.C. per Wk

၀င္အ ၀င္အ ၀င္အ

286.4 \$1,718

- 8 o 8

000

ဝဋ္ဌ ဝဋ္ဌ

E30 \$35.80

\$35.80

6340 Project Continuous Surveillance (2 Hours / Day)

6340 Develop Initial JSA & Input To Work Plans

6340 Assemble Planning Team

မင္တ မင္တ မင္တ

cess Estimating and Cost Management System	
Succ	

12

Page No.

10/24/2000

Project Name: WAG 3 Group 5 Wells Project Location: MTEC Estimate Number 2975-A		Ö	4STRUC	CONSTRUCTION DETAIL ITEM REPORT	ITEM REF	ORT	Client: Prepared By: Estimate Type	Clent: C. J. Roberts Prepared By: J. C. Grenz Estimate Type: Planning	oberts enz ig	
LEVEL Org/Subcontractor QTY	QTY	į	된	Crew/Rate	Labor	Const Eqp	Mati	SIC	Other	TOTAL
EK 1421.04.08.2 CM - CONDUCT OF OPERATIONS/CONT 6340 Schedule Work On POD (1 Hour / Day)	U.C. per WK	8.00	7 %	E30 \$35.80	143.2	° 2	° 9	° %	o g	143.2 \$859
6340 Outages (20 Hours / Outage)	U.C. per Ea	1.00	50 20 20	E30 \$35.80	716 \$716	° 0 5	o g	° <u>0</u>	° 9	716 \$716
6340 Subsurface Investigation (20 Hours / SI)	U.C. per Ea	1.00	88	E30 \$35.80	716 \$716	၀ ၀ွ	o g	o <u>o</u>	o o	716 \$718
00401400 6340 Pool Account (Direct Hours @ \$24 Per Hour)	U.C. per Hour	260.00	260	CN-CMOTHE \$11.36	11.36 \$2,954	0 0\$	o 9	o g	o o s	11.36 \$2,954
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$12,154 \$0 \$13,734	000	888	9 9 9	000	\$12,154 \$0 \$13,734
Subrotal Estimate Escalation Contingency					\$298 \$6,547	22	05 05 05	0,0	88	\$25,888 \$298 \$6,547
L TOTAL ER 1221.04.08.2 CM - CONDUCT OF OPERATIONS/CONDUCT OF MAINTENANCE	CONDUCT OF		517		\$32,733	0\$	\$0	2	OS.	\$32,733
- ER 1221.04.09 RADIATION CONTROL 7620 Radiological Control Technicians	U.C. per Wk	6.9	5 5	U60 \$24.66	248.6 \$986	0 9	00	o 9	00	246.6 \$986
7610 Radiation Control - Management Support - 10% OF RCT Total	U.C. per Hr	40.00	4	203 \$52.32	5.232 \$209	° 05	° <u>g</u>	0 0	o g ,	5.232 \$209
Subtotal Sales Tax INEEL ORG Labor/Subcontractor Overheads					\$1,186 \$0 \$1,064	\$ 8 S	2 S S	3 3 3	3 3 S	\$1,196 \$0 \$1,064
Subtotal Estimate Escalation Contingency					\$28 \$571	88	8 S	S S	9 S	\$2,260 \$28 \$571
-Total ER 1221.04.09 RADIATION CONTROL			2		\$2,857	0\$	8	2	S	\$2,857
GAPIF Non-Org G&A and PIF PF NOGAPIF Procurement Fee %	U.C. per \$	10,879.00	0		° 3	0 0	° 0 5	0 0\$	1 \$10,879	1 \$10,879

Project Name: WAG 3 Group 5 Wells Project Location: INTEC Estimate Number: 2975-A	VO3	CONSTRUCTION DETAIL ITEM REPORT	AIL ITEM REI	PORT	Client: Prepare Estimal	ed By: :e Type:	C. J. Roberts J. C. Grenz Planning	
LEVEL Org/Subcontractor — GAPIE Non-Org G&A and PIE G&A G&A Fee %	U.C. per \$ 4,134.00	Hrs Crew/Rate	Labor 0	Const Eqp	Mati	s/C	Other K,134	TOTAL 1 54,134
Subtorial Sales Tax Sales Tax INEEL ORG Labor/Subcontractor Overheads			989	2 2 2	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0.50	\$15,013 \$0 \$0	\$15,013 \$0 \$0
Subtotal Estimate Excatation Contingency			0,0,0	0,0	998	9 S	\$3,753	\$15,013 \$0 \$3,753
Total GAPIF Non-Org G&A and PIF		o	3.	S	o \$	2	\$18,766	\$18,766
Subtotal WAG 3 Group 5 Wells Sales Tax INEEL ORG Labor/Subcontractor Overheads			\$152,216 \$0 \$70,018	\$92,920 \$0 \$33,663	\$41,600 \$0 \$13,799	\$456,311 \$0 \$0	\$15,013 \$0 \$0	\$758,060 \$0 \$117,470
Subtotal Estimate Escalation Contingency			\$863 \$55,774	\$0 \$31,643	\$0 \$13,850	\$0 \$114,078	\$0 \$3,753	\$875,530 \$863 \$219,098
Total WAG 3 Group 5 Wells	-	4,666	\$278,871	\$168,217	\$69,249	\$570,389	\$18,766	\$1,095,491

[Editor's note: Appendix F, Project Schedule, does not include a flysheet.]

	: 6				,	
10 10 10 10 10 10 10 10	3	スエク・ウィング		(12/18.MM)		244 261 342 245 244 441 242 443 244 241 242
10 July 15 to 10 months 1 mon	00)	(B) (C)	200000	
10 13 15 10 10 10 10 10 10 10	000		0	03/16/20	0000	
10 15 15 10 10 10 15 15	100	:		高い地にたり	06/27/80	
Explication of the content of the content of content	0.13	1		06/22/00	06/22/00	
10.1 FT CF COLT. 10	1	7		06/22/00	06/22/00	
10 ct 10 c			7000	06/23/00	09/12/mg	
On of a cold from the late of t	7 6		8			
10 12 12 12 12 12 12 12	0 6		8	09/14/00	Opti a more	
10 or 3 or 3 to 1 to 1 to 1 to 2 or 3 or 3 to 3 to 3 to 3 to 3 to 3 to 3	201	-	320	Chart Science	CO 100 100 00 00 00 00 00 00 00 00 00 00 0	The state of the s
PACKAGE PACK	2		C	200000		
	4		3 4		10/30/00	The formation is a resident to
Cough 5 Febrer data Agrical Series Serie	020		No. 1	9000	10/30/00	Autoropie in the complete in t
OU 9-15 Group is Malp Paccorous in Facility Decicity on APPO 1701/000	54 54 54	Comment Resolution	9	10/31/00	11/14/00	
Cocoop a: Instance of Account of Instance of Account of Instance of Account of Instance of	127	OU 3-13 Group 5 MSIP Becomes	0	1718/00	11/30/00	
OU 3-13 t-3 d-3 d-3 d-3 d-3 d-3 d-3 d-3 d-3 d-3 d	100	2010 moses and 2010	8	13000	1/3000	
National Security Monitoring (17 wells) 3-44 30,000.000.000.000.000.000.000.000.000.0	7.00		70	02/23/01	0.5003006	
Microparties Samples Microparties Samples Microparties Samples Microparties Samples Microparties Samples Sam	65	1	8	62/23/01	02/23/61	
Out-state Sumples Out-	25		56	03/09/01	04/25/01	
224 000.00 0.07000 0.07000 0.07000 0.07000 0.07000 0.07000 0.07000 0.07000 0.07000 0.07000 0.07000 0.071	C	Antahaha	7	942661	08/27/01	rich mi
Sample Antibiosis (Comment) Samp	60		222	06/28/01	07/30/01	_, 14 W
Sample Analysis 20 wells) 42d 11/02/D1 61/11/02 61/11/02 62d 11/02/D2	1 12		Š	10/03/01	1101011	rŀ
Micropurge Sample Analysis 22d 01/1402 02/1202	300		436	11/02/01	0.77.00	
Micropurge Sampling (20 weils) 655 (00301) 011402	1 4		No. of the last of	13-3 74 B 25-35		
Sample Validation MITEC Abutage Sample Analysis 44d 0111002 02111002 02111002 Nivropurge Sample Analysis Sample Validation 22d 0211502 0411602 0411602 0411602 Nivropurge Sample Report 22d 0211002 0411602 0411602 0511002 0511002 Comment Resolution (March March and Comments) 22d 0211002 0411602 0411602 0411602 DOS-EDEE AUDHAY Review and Comments 22d 0211002 0411602 0411602 0411602 Sample Analysis (20 wells) 22d 0411602 0411602 041602 041602 Sample Analysis (20 wells) 22d 0411002 041602 041602 041602 NTEC Abutant Review and Comment 22d 0411003 0416002 0416003 0416003 ODE-LOEP Analysis (20 wells) 22d 0411003 0410003 0410003 0410003 0410003 ODE-LOEP Analysis (20 wells) 22d 0411003 0410003 0410003 04100003 ODE-LOEP Analysis (20 wells) 22d <td>5</td> <td>of soften for the fine</td> <td>Y</td> <td>10,000</td> <td>76/15/05</td> <td></td>	5	of soften for the fine	Y	10,000	76/15/05	
Sample Validation 22d 04/15/02 04/15/02 Agency Review and Comment 22d 04/15/02 04/15/02 Comment Resolution 10d 05/15/02 05/15/02 Comment Resolution 10d 05/15/02 05/15/02 ONE-LOFE AUTHORN Review and Comments 22d 02/15/02 04/15/02 Analysis (20 wells) 22d 03/15/02 04/15/02 Sample Validation 22d 04/15/02 04/15/02 ONE-LOFE AUTHORN Review and Comment 22d 04/15/02 04/15/02 Sample Validation 22d 04/10/02 01/10/03 Sample Validation 22d 04/10/03 01/10/03 Sample Validation 22d 04/10/03 01/10/03 Sample Validation 22d 04/10/03 01/10/03 DE-LOFE AUTHORN Review and Comments 22d 04/10/03 05/10/03 OB 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 04/10/03 05/10/03 OB 3-15 INTEC Aboritoring Verial Annual Report 22d 04/10/03 05/10/03	ġ.		4.4.4	- No. 10 to	017170	
Agency Light Results Report 22 d Out 160 2 Ou	00		7 66	Car I will a	03/14/02	
Agenory Roview and Comment 10d 05/15/02 05/15/02 10d 05/15/02 10d 05/15/02 <td>80</td> <td></td> <td>25.6</td> <td>0.377.377.2</td> <td>20/10/20</td> <td></td>	80		25.6	0.377.377.2	20/10/20	
Comment Resolution OSTABLE 05/30/22 05/30/22 05/30/22 ONE-LOE FEALINH Wells Annual Report 22d 02/13/22 02/13/22 07/13/22 07/13/22 ONE-LOE FEALINH Wells Annual Report 22d 02/13/22 02/13/22 07/13/22 1 ON 9-13 NTEC Facility Monthoring (Second Annual Sampling) 22d 04/18/02 04/18/02 1 Sample Analysis (20 wells) Sample Analysis (20 wells) 10.02/20/22 10.02/20/22 1 Sample Analysis (20 wells) Sample Analysis (20 wells) 22d 04/11/03 02/16/03 1/10/20/32 Sample Analysis (20 wells) Sample Analysis (20 wells) 22d 01/10/20/32 04/10/23 1/10/20/32 Sample Analysis (20 wells) Sample Analysis (20 wells) 22d 01/10/23 04/10/23	200			289.283	200.00	
WTEC Monitoring Weils Annual Report 10dd 05/31/02 04/13/02 06/13/02 DOE-IOFE A/ICHIY Review and Comment 22d 03/13/02 04/15/02 04/15/02 OU 3-13 WITEC Facility Monitoring (Second Annual Sampling) 22d 04/15/02 01/15/02 10/23/02 Sample Analysis (20 weils) 22d 04/15/02 01/10/03 02/10/03 10/23/02 Sample Analysis (20 weils) 22d 03/11/03 02/10/03 01/10/03 02/10/03 Sample Analysis (20 weils) 22d 03/11/03 04/10/03 02/10/03 02/10/03 NITEC Monitoring Weils Annual Report 22d 03/11/03 04/10/03 04/10/03 04/10/03 OU 3-13 WITEC Facility Monitoring (Third Annual Sampling) 22d 03/11/03 04/10/03 02/10/03 02/10/03 Sample Validation WITEC Monitoring Weils Annual Report 22d 03/10/04 02/05/04 02/10/05 DOE-ID/EPA/IDHW Review and Comment 22d 03/10/04 02/10/05 04/10/04 02/10/05 DOE-ID/EPA/IDHW Review and Comment 22d 04/10/04 05/	660		2	20/00/20	20/08/50	
DOE-ID/PE A/IDHW Review and Comment 22d 02/13022 04/15/02	0		200	05/21/02	06/13/02	
Incorporate DOE-ID/EPAIDHW Review Comments 22d 04/16/02 05/15/02 05/15/	100 h		229	02/13/02	03/14/22	
OU 3-13 NTEC Facility Monitoring (Second Annual Sampling) 22d 04/18/02 10/28/02 10/28/02 10/28/02 Sample Analysis (20 wells) 22d 01/10/03 01/10/03 02/10/03 02/10/03 Sample Validation NTEC Monitoring Wells Annual Report 22d 01/10/03 02/10/03 02/10/03 NTEC Monitoring Wells Annual Report 22d 03/11/03 03/10/03 05/09/03 0 OU 3-13 INTEC Facility Monitoring (Third Annual Sampling) 22d 04/10/03 05/09/03 01/07/04 Sample Validation 22d 04/10/03 05/09/03 01/07/04 02/06/04 Sample Validation 22d 04/10/03 05/09/03 01/07/04 02/06/04 NTEC Monitoring Wells Annual Report 20d 02/10/03 01/07/04 02/06/04 DOE-ID/EPA/IDHW Review Comments 22d 04/07/04 03/06/04 03/06/04 DOE-ID/EPA/IDHW Review Comments 22d 03/06/04 03/06/04 03/06/04 DOE-ID/EPA/IDHW Review Comments 22d 04/07/04 05/06/04 05/06/04 <	0		n N	THE THE	C41502	
Sample Validation 22d 09/30/02 10/29/02 Sample Validation 44d 10/30/02 01/09/03 INTEC Monitoring Wells Annual Report 22d 01/10/03 02/11/03 DOE-ID/EPA/IDHW Review and Comment 22d 02/11/03 03/10/03 Incorporate DOE-ID/EPA/IDHW Review Comments 22d 04/10/03 04/10/03 Sample Analysis (20wells) 22d 04/10/03 01/09/04 Sample Validation 22d 04/10/03 01/09/04 ODE-ID/EPA/IDHW Review and Comment 22d 01/09/04 02/09/04 ODE-ID/EPA/IDHW Review and Comments 22d 01/09/04 02/09/04 ODE-ID/EPA/IDHW Review Comments 22d 04/07/04 03/06/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 04/07/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d	000		220	04/16/02	10 10 10 10 10 10 10 10 10 10 10 10 10 1	
Sample Validation 44d 10/30/02 01/09/03 INTEC Monitoring Wells Annual Report 22d 01/10/03 02/10/03 DOE-DICEAUDIF Annual Review Comments 22d 02/11/03 04/09/03 Incorporate DOE-LIDER Annual Review Comments 22d 03/11/03 04/09/03 OU 3-13 INTEC Facility Monitoring (Third Annual Sampling) 22d 04/10/03 05/09/03 Sample Analysis (Zowells) 44d 10/28/03 01/07/04 Sample Velidation 22d 01/07/04 02/06/04 Sample Velidation 22d 01/08/04 02/06/04 DOG-LIDEP AnDHW Review and Comment 22d 01/08/04 03/06/04 DOG-LIDEP ANDHW Review Comments 22d 03/08/04 04/06/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 04/07/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d	2)	Samue analysis (35 materials)	S. S.	09/30/02	10/29/02	
INTEC Monitarium 22d 01/10.003 02/10.003 02/10.003 DOE-ID/Fe Monitarium Weits Annual Report 20d 02/11/03 03/10/03 04/09/03 DOE-ID/Fe PAUDHW Review and Comments 22d 03/11/03 04/09/03 66/09/03 Incorporate DOE-ID/Fe PAUDHW Review and Comments 22d 04/10/03 05/09/03 66/09/03 OU 3-13 NIVEC Facility Monitoring (Third Annual Sampling) 22d 04/10/03 05/09/03 66/09/03 Sample Validation 22d 01/09/04 02/06/04 60/06/04 60/06/04 INTEC Monitoring Weils Annual Report 20d 02/09/04 02/06/04 60/06/04 DOE-ID/EP AIDHW Review and Comments 22d 03/06/04 60/06/04 60/06/04 DOE-ID/EP AIDHW Review and Comments 22d 04/07/04 65/06/04 65/06/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 10/07/04 11/05/04	is		244	10/30/02	01/09/03	The state of the s
POE-ID/EPA/IDHW Review and Comment 20d 02/11/03 03/10/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/03 04/09/04 02/09/04 02/09/04 02/09/04 02/09/04 04/09/04	, q		223	01/10/03	23/1032	
OUE-LDEPAIDHW Review and Comments 22d 03/11/03 04/09/03 Part of the comments Incorporate DOE-ID/EPA/IDHW Review Comments 22d 04/10/03 05/09/03 Part of the comments OUI 3-13 INTEC Facility Monitoring (Third Annual Sampling) 22d 04/10/03 05/09/03 Part of the comments Sample Analysis (20)vells) Sample Analysis (20)vells) 01/07/04 Part of the comments Part of the comments INTEC Monitoring Wells Annual Report 22d 01/08/04 02/05/04 Part of the comments DOE-ID/EPA/IDHW Review and Comments 22d 04/05/04 04/05/04 Part of the comments OUI 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 10/07/04 10/07/04 10/07/04		Mark Soniorne Wells Annual Report	8	02/11/03	236425	
Incorporate DOE-ID/EPA/IDHW Review Comments	7	Control of the Contro	234	02/11/03	000000000000000000000000000000000000000	
OUI 3-13 INTEC Facility Monitoring (Third Annual Sampling) 22d 09/26/03 10/27/03 Sample Analysis (20wells) Sample Analysis (20wells) 10/28/03 01/07/04 Sample Velidation 22d 01/08/04 02/06/04 INTEC Monitoring Wells Annual Report 20d 02/08/04 03/08/04 DOE-ID/EPAIDHW Review and Comments 22d 03/08/04 04/06/04 Incorporate DOE-ID/EPAIDHW Review Comments 22d 04/06/04 05/06/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 1007/04 11/05/04	3	Incorporate DOE-DIEPARDHW Review Comments	200	26.7.80	And the state of t	
Sample Analysis (20wells) 44d 102803 01/07/04 Sample Validation 22d 01/08/04 02/06/04 INTEC Monitoring Wells Annual Report 20d 02/08/04 03/06/04 DOE-ID/EPA/IDHW Review and Comment 22d 03/08/04 04/06/04 Incorporate DOE-ID/EPA/IDHW Review Comments 22d 04/06/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 04/07/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 1/05/04		00 3-13 NTEC FESHY Monitoring (Third Annual Sampling)	200	2020		
Sample Validation 10/07/04 INTEC Monitoring Wells Annual Report 22d 01/08/04 02/06/04 DOE-ID/EPA/IDHW Review and Comment 22d 03/08/04 04/06/04 Incorporate DOE-ID/EPA/IDHW Review Comments 22d 04/07/04 05/06/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 1/05/04	0		The state of the s	W. C.		
INTEC Monitoring Wells Annual Report	S	Sample Volidation	7 60	\$00000 m	01/07/54	
DOE-ID/EPA/DHW Review and Comment Incorporate DOE-ID/EPA/DHW Review Comments OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 04/07/04 1/05/04		MIEC Montoring Wells Annual Report	200	98920	02/06/04	
Incorporate DOE-IDEPA/IDHW Review Comments 22d 03/08/04 04/07/04 OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 1007/04 11/05/04	5	OOE-DEPAIDHY Review and Comment	707	0.550	68686	The second state of the se
OU 3-13 INTEC Facility Monitoring (Fourth Annual Sampling) 22d 1007/04	00	Incorporate DOE-ID/EPA/IDHW Review Comments	077	0.1708.04	04/06/04	
	0	OU 3-12 INTEC Facility Monitoring (Fourth Annual Commised)	777	04/07/04	05/05/04	
	Total Comme	The state of the s	220	1007/04	11/05/04	

Figure F-1. Schedule for monitoring system and installation plan, OU 3-13. Group 5, Snake River Plain Aquifer.

505520 505520 505520 505520 505520 505520 505520 505520 501110 50580 50580 50700 50720

50730 50730 50730 50778 50778 50738 50790 50800 50836 50836 51112 50890 50890 50910 50930 50930 50930 50950 \$ 1016 \$ 1016 \$ 1116

10010

02803 02803

できた

Appendix G

Health and Safety Plan for Operable Unit 3-13, Group 5, Snake River Plain Aquifer

INEEL/EXT-2000-00817 Revision 0

[The document that is the subject of this appendix was provided as an attachment to the original deliverable.]

To view this Appendix, please see specific "Stand Alone" document number

Appendix H

Waste Management Plan for Operable Unit 3-13, Group 5, Snake River Plain Aquifer Project

DOE/ID-10829 Revision 1

[The document that is the subject of this appendix was provided as an attachment to the original deliverable.]

APPENDIX H

DOE/ID-10829 IS ERRONEOUSLY LISTED AS REVISION 1 (REV.01) – REVISION 2 (REV.02) IS THE CORRECT REVISION NUMBER

Appendix I Quality Level Designation and Record

414.02 11/10/98 Rev. 02

QUALITY LEVEL DESIGNATION AND RECORD

Quality Level Evaluation Performed By:	R. G. Thompson	Date: <u>5/15/00</u>
Facility/Structure/System: OU 3-13 Snak	e River Plain Aquifer	Quality Level: 3
IDENTIFICATION OF ITEM	QUALITY LEVEL DESIGNATION	TECHNICAL JUSTIFICATION
Well Drilling & Completion	3	INEEL/INT-2000-00036
Well Sampling & Analysis	3	INEEL/INT-2000-00036
		•
<u> </u>		
	accordance with MCP-540, and obtain appl assurance record. (Master Equipment List	
D C Thompson		
R. G. Thompson Quality Assurance Concurrence Printed/Typed Name	Quality Assurance Concurrence Signature	ce 3//2/2000 Date
C. J. Roberts		
Facility/Program/Project Approval Printed/Typed Name	Facility/Program/Project Appro Signature	val Date

431.02 08/12/98 Rev. 06

ENGINEERING DESIGN FILE

Functional File No. <u>INEEL/INT-99-00723</u>

EDF No. <u>EDF-ER-076</u>

Page 1 of 1

4 Buston Pilo No		O Brain of Work Old 2 42 De	OCT DOD OBOUNDWATER MONI	TODING
1. Project File No.		2. Projecti rask OU 3-13 Pr	OST-ROD GROUNDWATER MONI	TORING
3. Subtask Hazard Classific	cation			
•				
4. Title: INTEC Groundwate	er Monitoring	Well Drilling Hazard Classific	cation	
5. Summary: The purpose of	f this Engine	ering Design File is to docum	nent the hazard classification of the	INTEC
groundwater monitoring well under the auspices of a Hea	l drilling proje alth and Safet	ct and to support the determ v Plan.	nination that the project can be safel	y conducted
6. Distribution (complete pa				
Distribution (summary pa				
7. Review (R) and Approval	(A) Signature	95:		
	R/A	Printed Name	Signature	Date
Author	R	Tharan L. Cook	Tharane Cash	1/12/99
Independent Verification	R	Rodney Peatross	Roll Peatron	7/15/89,
Requestor	A	Carlton Roberts	Jaan	2/0/9
			(9	/ / /
				,
	 			

431.12 08/24/98 Rev. 01

REQUEST FOR DETERMINATION OF SAFETY ANALYSIS REQUIREMENTS

				Date: July 14, 1999
A.	То Ве	e Completed by Project Manager, Project Management Departmen	t	
	1.	Project OU 3-13 Post-Rod Groundwater Monitoring		
		Project Manager Robert E. James		Mail Stop 3953
		Type: ☐ Line Item ☐ GPP ☐ CE ☐ Work Order ☒	Other ER Project	
	2.	Reference Documents Submitted:		
		Check the documents submitted with this request: Technical Functional Requirements Design Criteria Conceptual Design Report Environmental Evaluation or EIS USQ Screening Feasibility Study Project Plan Work Order Engineering CI		
В.	То Ве	e Completed by the Cognizant Safety Analysis Organization		
	Task	Number		
	1.	New Facility Project:		
		PSAR required before facility construction? New SAR or revision/addendum to an existing SAR required before operation? Will this be a nuclear facility (see MCP-2446)?] Yes ⊠ No	
	2.	This and so a reason, (essential service).	, 163 Ø 160	
	۷.	Existing Facility Modifications: USQ evaluation required? Revision/addendum to an existing SAR required? Descriptive changes to an existing SAR required? Hazard category/classification Other Industrial		EH 7/27/27
	3.	Justification for Items B.1 - B.2:		
		See attached hazard classification		
	4.	Proposed schedule for Company and DOE approvals of required Saf	ety Analysis:	
Req	uest fo	r Safety Analysis Approval	,	
	E	. E. Hochhalter E. E. H	vehlle.	7/27/77
-		nager, Safety Analysis Unit/Department Manager, Safety Ana	lysis Unit/Department ature	Date

Distribution: Copy for Project Manager; original and one copy to Safety Analysis. Original back to Project Manager when Safety Analysis determination is completed.

OU 3-13 GROUNDWATER MONITORING HAZARD CLASSIFICATION

SUMMARY

The purpose of this hazard classification is to present an evaluation of the potential hazards associated with proposed OU 3-13 groundwater monitoring well drilling activities that could affect the public, the workers, or the environment. This evaluation is based on preliminary project information, the draft OU 3-13 Record of Decision (ROD), and data collected through previous sampling activities.

HAZARD CLASSIFICATION

Groundwater monitoring well construction activities are classified as "other industrial," based on the guidance presented in DOE-STD-1027-92, *Hazard Categorization and Accident Analysis Techniques for Compliance with DOE Order 5480.23, Nuclear Safety Analysis Reports*, DOE-ID N 420.Al, *Safety Basis Review and Approval Process*, and DOE-EM-STD-5502-94, *Hazard Baseline Documentation*, and the OU 3-13 ROD. No appreciable hazardous waste or hazardous chemical quantities have been identified in this hazard classification; nevertheless, the project will be conducted under the administrative control of a health and safety plan (see Appendix G to this report) to ensure compliance with applicable occupational safety and health standards.

1. INTRODUCTION

This project consists of three separate well drilling operations in and around the Idaho Nuclear Technology and Engineering Center (INTEC). These activities, and other INTEC remedial actions, are identified and divided into seven groups, in the INTEC Record of Decision (INEEL 1999). This evaluation addresses the construction of new groundwater monitoring wells planned for Group 5, Snake River Plain Aquifer. Another well drilling operation is planned for monitoring a new INTEC CERCLA Disposal Facility; however, since the location of the facility has not been determined as of this writing, it will not be specifically addressed herein.

2. DESCRIPTION

2.1 OU 3-13, Group 5, Snake River Plain Aquifer

The Snake River Plain Aquifer (SRPA) lies beneath the INTEC at a depth of approximately 450 ft and has been contaminated through operation of injection well CPP-23. Additionally, contaminated soils and perched water have been predicted to continue to contribute contaminants. This project consists of deepening four wells and drilling one new monitoring well south of the INTEC in the zone predicted to contain the highest concentration of I-129 contamination. The wells will be monitored and sampled to determine the need for further remediation and will be drilled to a depth of approximately 650 ft. The locations of the four wells to be deepened and the proposed location of the new well are shown in Figure I-1.

3. HAZARDOUS MATERIAL INVENTORY

3.1 Groundwater Contaminants

DOE Order 5480.23, *Nuclear Safety Analysis Reports*, requires that radioactive and chemical materials be inventoried by type and amount. Those quantities of material are then to be evaluated using the guidance presented in DOE-STD-1027-92 and DOE-EM-STD-5502-94, to establish facility or project hazard categorization. In this case, due to the extremely low quantities of material expected to be encountered during well drilling activities, the inventory of contaminants has been taken from groundwater sampling results that are presented in the Remedial Investigation/Feasibility Study. The values selected are provided in Table I-1.

Table I–1. Groundwater sample results.

Snake River Plain Aquifer					
Contaminant	Concentration	TQ/RQ			
Sr-90	84 pCi/L	1.6E+01 Ci/ 1.0E-0l Ci			
tritium	30,700 pCi/L	1.0E+03 Ci/ 1.0 Ci			
Tc-99	448 pCi/L	1.7E+03 Ci/ 10 Ci			
I-129	3.8 pCi/L	6.0E-02 Ci/ 1.0E-03 Ci			
magnesium	63 μg/L	NA			
a. TQ = Threshold Quantity, DOE-S' RQ = Reportable Quantity, 40 CFI					
b. Not listed in 40 CFR 302, Table 30	2.4				

3.2 Evaluation

A comparison of the contaminant concentrations to the Threshold and/or Reportable Quantity values shows that many orders of magnitude exist between the levels of radioactive and chemical contaminants expected to be encountered during these well drilling projects, and the classification thresholds. On this basis, there are no radiological or chemical hazards associated with this project. The releasable quantities of contaminants associated with the well drilling activities would be so small as to be negligible and would result in no threat to the workers, the environment, or the public.

Further, Figure I-1 presents an overlay of the proposed locations of the Group 5 monitoring wells and the existing Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) sites inside the INTEC security fence. As can be seen on the drawing, there are no conflicts between proposed well locations and the sites, therefore, none of the wells will be drilled into potential underground hazards and no further analysis is necessary.

3.3 General Project Hazards

Table I-2 lists the potential general hazards associated with the OU 3-13 groundwater monitoring well drilling project activities. This list cites common and project-specific hazards, specifies whether they are applicable to the project, identifies the appropriate occupational health and safety standards, and assesses each hazard as being routine or significant. Any hazards determined to be significant are analyzed further while routine hazards will be addressed in the project health and safety plan (Appendix G to this report).




Figure 1-1. Locations of monitoring wells to be deepened to sample HI interbed and location of new well.

 Table
 I-2. Potential general project hazards.

Hazard	Applicable	OSHA/DOE Standard	Routine/Significant
High Voltage (>600 V)	Yes	29 CFR 1910.308(a), .304(f)(7), .303(h)(2), .303(h)(3), .303(h)(4)	Routine
Flammable gases, liquids, or dust	Yes	29 CFR 1910.106, .120, .144, .1200; 29 CFR 1926.152	Routine
Compressed gases	Yes	29 CFR 1910	Routine
Explosive materials	No	NA	NA
Cryogens	No	NA	NA
Inert and low-oxygen atmospheres (confined spaces)	No	NA	NA
Chemical exposures	No	NA	NA
Nonionizing radiation	No	NA	NA
High-intensity magnetic fields	No	NA	NA
High noise levels	Yes	29 CFR 1910.95, .1200; 29 CFR 1926.52	Routine
Mechanical and moving equipment	Yes	29 CFR 1910.147, .211; 29 CFR 1926, Subpart W	Routine
Working at heights	Yes	29 CFR 1910.25, .28; 29 CFR 1926.951, .451	Routine
Excavation	No	NA	NA
Material handling	Yes	29 CFR 1910.120, .176, .178, .184; DOE-STD-1090-96, "Hoisting and Rigging"	Routine
Aircraft collision	No	NA	NA
Pesticide use	No	NA	NA
High temperature (>125°F on contact or >202°F) and pressure (>25 psig for gas or vapor, or >200 psig for a liquid system)	Yes	29 CFR 1910.120, .1200	Routine
Inadequate illumination	No	NA	NA
Radiological hazardous materials	No	NA	NA
Nuclear criticality	No	NA	NA
Direct radiation	No	NA	NA
Construction	Yes	29 CFR 1926	Routine
Pyrophoric metals	No	NA	NA
Natural phenomena - floods, volcanic activity, earthquakes, etc.	No	NA	NA

4. CONCLUSIONS

4.1 Hazard Classification

Based on the information presented above, the hazard classification of the OU 3-13 groundwater monitoring well drilling project is determined to be "other industrial." No releasable quantities of hazardous or radioactive materials have been identified, therefore, this project will not present significant, non-routine concerns to the workers, the public, or the environment. There are no general project hazards that have been identified as "significant," therefore, no further analysis is required. Those general project hazards that have been identified as "routine" will be addressed and administratively controlled through the project health and safety plan (Appendix G to this report).

5. REFERENCES

- 1. 40 CFR 302, July 1999, "Designation, Reportable Quantities, and Notification," *Code of Federal Regulations*, Office of the Federal Register.
- 2. DOE Order 5480.23, Nuclear Safety Analysis Reports, U.S. Department of Energy, March 10, 1994.
- 3. DOE-STD-1027-92, Hazard Categorization and Accident Analysis Techniques for Compliance with DOE Order 5480.23, Nuclear Safety Analysis Reports, Change Notice No. 1, U.S. Department of Energy, September 1997.
- 4. DOE-EM-STD-5502-94, Hazard Baseline Documentation, U.S. Department of Energy, August 1994.
- 5. DOE-ID N 420.Al, *Safety Basis Review and Approval Process*, U.S. Department of Energy, Idaho Operations Office, May 1998.
- 6. INEEL, Comprehensive RI/FS for the Idaho Chemical Processing Plant OU 3-13 the INEEL Part A, RI/BRA Report (Final), DOE/ID-10534, U. S. Department of Energy, Idaho Operations Office, November 1997.
- 7. INEEL, Final Record of Decision, Idaho Nuclear Technology and Engineering Center, Operable Unit 3-13, DOE/ID-10660 Revision 0, October 1999.

Appendix J

Quality Assurance Project Plan for Waste Area Groups 1, 2, 3, 4, 5, 6, 7, 10, and Inactive Sites

DOE/ID-10587 Revision 6

[The document that is the subject of this appendix was provided as an attachment to the original deliverable.]

To view this Appendix, please see specific "Stand Alone" document number

Appendix K Spill Prevention/Response Program

Appendix K

Spill Prevention/Response Program

Any inadvertent spill or release of potentially hazardous materials (such as equipment fluids) will be subject to the substantive requirements contained in the INEEL Emergency Plan/RCRA Contingency Plan Implementing Procedures manual (PLN-114). The Table of Contents for the companywide plan, PLN-114, plus the Table of Contents and Addendum 2 for the Idaho Nuclear Technology and Engineering Center PLN-114-2, are attached.

Handling of the material and/or substance shall be in accordance with the recommendations of the applicable material safety data sheets, which will be located at the project site(s). In the event of a spill, the emergency response plan outlined in the project HASP will be activated. All materials/substances at the work site shall be stored in accordance with applicable regulations in approved containers.

Idaho National Engineering		412.09 (11/05/2001 – Rev. 06)	
INEEL Emergency Plan/ RCRA Contingency Plan INTEC	TABLE OF CONTENTS	Identifier: Revision: Page:	PLN-114-2 90 1 of 4
Document Control Center: (208) 526-1202	Document Owner: Director, Emergency Preparedness	Effective Date:	06/10/02
M 16A2 Emergency F d dden INTE	ic .	Change Number	r: <u>N/</u>

TAB	SECTION OR DOCUMENT TITLE	REV.
1	Introduction	4
2	Emergency Response Organization	3
3	Offsite Response Interfaces	3
4	Operational Emergency Event Classes – <u>Temporary Field Change</u> #91042 until 01/31/03	5
5	Notifications and Communications	3
6	Consequence Assessment	3
7	Protective Actions	5
8	Medical Support	3
9	Recovery and Reentry	3
10	Public Information	3
11	Emergency Facilities and Equipment	6
12	Training	3
13	Drills and Exercises	3
14	Program Administration	3
	APPENDICES	
D	APPENDIX D – ICPP Maps	6
G	APPENDIX G – Spill Plan	5
Н	APPENDIX H - ICPP Emergency Equipment	5
I	APPENDIX I – Emergency Action Managers	8

Form 412.09 11/05/2001 - Rev. 06

			11700,2001 110.701
INEEL Emergency Plan/	TABLE OF CONTENTS	Identifier:	PLN-114-2
RCRA Contingency Plan		Revision:	90
		Page:	2 of 4
INTEC			

TAB	SECTION OR DOCUMENT TITLE	REV.
L	APPENDIX L - CPP-1647 - Canceled - TAA Closed	
Ll	APPENDIX L1 - CPP-627 - Superseded by Appendix L1 of PLN-114-2	
L2	APPENDIX L2 – NORTH OF ICPP TR-35 – <u>Canceled – TAA Closed</u>	
L3	APPENDIX L3 – TAA CPP-620-HIBAY-02 – <u>Canceled – TAA</u> <u>Closed</u>	
L4	APPENDIX L4 – TAA CPP-637-113-09	8
L5	APPENDIX L5 – TAA CPP-637-HILO-16 – <u>Canceled – TAA Closed</u>	
L6	APPENDIX L6 – TAA CPP-659 416-A	8
L7	APPENDIX L7 – TAA CPP-601-PM-A – Canceled – TAA Closed	
L8	APPENDIX L8 - CPP-602-227-03 - Canceled - TAA Closed	
L9	APPENDIX L9 - CPP-684-Warmside-04 - Canceled - TAA Closed	
L10	APPENDIX L10 - CPP-627-SAL-06 - Canceled - TAA Closed	
L11	APPENDIX L11 - CPP-602-209-11 - Canceled - TAA Closed	
L12	APPENDIX L12 - CPP-602-224-14 - Canceled - TAA Closed	
L13	APPENDIX L13 - CPP-1677-126-A - Canceled - TAA Closed	
L14	APPENDIX L14 - CPP-663-HOTSHOP-A	6
L15	APPENDIX L15 - CPP TB55-000-A - Canceled - TAA Closed	
L16	APPENDIX L16 - CPP-701-BERM-A - Canceled - TAA Closed	
L17	APPENDIX L17 - CPP-604-WO-A - Canceled - TAA Closed	
L18	APPENDIX L18 - Canceled - TAA Closed	
L19	APPENDIX L19 - CPP-1618-000-A - Canceled - TAA Closed	

Form 412.09 11/05/2001 - Rev. 06

INEEL Emergency Plan/	TABLE OF CONTENTS	Identifier:	PLN-114-2
RCRA Contingency Plan		Revision:	90
INTEC		Page:	3 of 4

TAB	SECTION OR DOCUMENT TITLE	REV.
L20	APPENDIX L20 - CPP-1789-000-A	8
L22	APPENDIX L22 - CPP-666-V131-A - Canceled - TAA Closed	
L23	APPENDIX L23 - CPP-666-V132-A - Canceled - TAA Closed	
L24	APPENDIX L24 - CPP-666-216-A - Canceled - TAA Closed	
L25	APPENDIX L25 - CPP-602-BSMT-A - Canceled - TAA Closed	
L26	APPENDIX L26 – TAA for CPP-659-427-A – <u>Canceled – TAA</u> <u>Closed</u>	
L27	APPENDIX L27 – TAA INTEC-659-LVC-A – <u>Canceled – TAA</u> <u>Closed</u>	
L28	APPENDIX L28 – CPP-653-000-A	9
L29	APPENDIX L29 – TAA CPP-659-DVC-A	2
L30	APPENDIX L30 - TAA CPP-659-419 - Canceled - TAA Closed	
L31	APPENDIX L31 - CPP-708-RATA-B - Canceled - TAA Closed	
L32	APPENDIX L32 - CPP-1618-000-B - Canceled - TAA Closed	
L33	APPENDIX L33 – TAA CPP-1619-000-A	0
L34	APPENDIX L34 – CPP-TFSP-ECA97-A	2
L35	APPENDIX L35 -INTEC-CPP-601-PM-B - Canceled - TAA Closed	
L36	APPENDIX L36 – CPP-659-323-A	1
L37	APPENDIX L37 – INTEC-606-ES-A – Canceled – TAA Closed	
L38	APPENDIX L38 INTEC-659-LEV3-A - Canceled - TAA Closed	
L39	APPENDIX L39-INTEC-TFA Soil Piles	0
L40	APPENDIX L40-INTEC-U 3-13 PERCHED WATER DRILLING – Canceled - TAA Closed	
L4t	APPENDIX L41-RCRA CONTINGENCY PLAN – <u>Canceled TAA</u> <u>Closed</u>	
L42	APPENDIX L42 CPP-669-000-A	Ī
L43	APPENDIX L43 - CPP-708-STACK-A	ī
L44	APPENDIX L44 – CPP TANK FARM-782-A <u>Canceled - TAA</u> <u>Closed</u>	

INEEL Emergency Plan/	TABLE OF CONTENTS	Identifier:	PLN-114-2
RCRA Contingency Plan		Revision:	90
INTEC		Page:	4 of 4

The second secon	
* E* A . C	SECTION OR DOCUMENT TITLE
I ADMAR	
	AND THE RESIDENCE AND ADDRESS OF A STREET
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7 * ***********************************

L45 APPENDIX L45 – CPP-708-STACK-B – <u>Canceled - TAA closed</u>

412.09 (11/05/2001 - Rev. 06) Idaho National Engineering and Environmental Laboratory INEEL Emergency Plan/ ADDENDUM 2, IDAHO NUCLEAR Identifier: PLN-114-2 Revision: RCRA Contingency Plan TECHNOLOGY AND ENGINEERING CENTER (INTEC), Page: G1 of G25 APPENDIX G INTEC Facility Document Control Center: (208) 526-1202 SPILL PLAN Document Owner: Manager, Emergency Effective Date: 06/10/02 Management

87868

CONTENTS

G1.	RELE	ASE, SPILL, OR LEAK OF HAZARDOUS MATERIAL	G3
	G1.1	General	G3
	G1.2	Radiological	G4
	G1.3	Nonradiological	G4
G2.	ACTIO	ONS TO BE TAKEN IN RESPONSE TO A RELEASE, SPILL, OR LEAK	G4
	G2.1	Remedial Actions for Leaking Process Components and Other Equipment	G6
	G	2.1.1 Leakage From/Without Secondary Containment (2.1.2 Leakage From Primary To Secondary Containment (High Integrity)	G7
	G	2.1.3 Leakage From Primary To Secondary Containment (Limited Integrity)	G9
G3.	SPILL I	PREVENTION CONTROL AND COUNTERMEASURES PLAN	G11
	G3.1	General Information	G112
		3.1.1 Regulatory Background	
	G3.2	Spill Events	G14
	G3.3	Oil Storage Capacity	G14
	G3.4	Oil Flow Direction and Facility Drainage	G16
	G3.5	Oil Spill Containment and Diversionary Structures And Equipment	G18
	G3.6	Miscellaneous Control Measures	.G20
	G3.7	Fail-Safe Engineering	.G20
	G3.8	Wastewater Effluent	.G21

INEEL Emergency Pla RCRA Contingency Pl	an TECHNOLOGY AND Re	evision:	PLN-114-2 5
INTEC Facility	ENGINEERING CENTER (INTEC), Pa APPENDIX G SPILL PLAN	nge:	G2 of G25
G3.9 Correcti	on Of Oil Leaks	·····	G21
G3.10 Portable	:/Temporary Tanks		G21
G3.11 Spill Re	sponse	······································	G21
G3.12 Tank Tr	uck Loading and Unloading	······	G23
G3.13 Inspection	on and Records		G23
G3.14 Security	·		G24
	el, Training, and Spill Prevention		G24

FIGURES

G1.

G1.	Location of the INTEC within INEEL boundaries	.G13
G2.	INTEC facility map	.G17

TABLES

G3.3.1	Aboveground storage tanks	.G15
G3.3.2	Underground storage tanks	.G16
G3.3.3	Transformers 660 gallons or greater	.G16

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
-	ENGINEERING CENTER (INTEC),	Page:	G3 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

G1. RELEASE, SPILL, OR LEAK OF HAZARDOUS MATERIAL

G1.1 General

Hazardous chemicals and fuel in various quantities are used and stored throughout the Idaho Nuclear Technology and Engineering Center (INTEC). Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) low-level radioactive, mixed low-level radioactive, Toxic Substances Control Act (TSCA) polychlorinated biphenyl (PCB), hazardous, and/or special case waste will be disposed outside the INTEC facility fence at the Idaho National Engineering Environmental Laboratory (INEEL) CERCLA Disposal Facility (ICDF) complex. This complex includes the Storage, Sizing, Staging, and Treatment Facility (SSSTF) with administration and decontamination buildings and associated units, storage/staging pads, an evaporation pond with two cells, one landfill disposal cell, leachate collection system and associated equipment.

Substances could be released (a) during an accident involving handling of the substances; (b) as a result of a more general emergency, such as a fire, explosion, or tank failure; or (c) pipeline valving that has deteriorated. A list of hazardous chemicals handled or stored in an area is included as appropriate in facility-specific information for that area. The lists specify the maximum quantity of material allowed, although typical quantities may be significantly less. Personnel are trained to consult these lists, appropriate material safety data sheets, and appropriate emergency response procedures before approaching any area or accident involving a chemical leak or spill.

If an emergency or response to a hazardous material is necessary that requires the use of Level A personal protective equipment (PPE), the emergency action manager directs activation of the Incident Response Team (IRT), if available. The emergency action manager may request additional assistance from the INEEL HazMat Team as needed.

NOTE: IRT will use the buddy system and have a minimum of two backup personnel ready in appropriate levels of PPE, if rescue is needed.

All other personnel evacuate the immediate area. Personnel outside of that area remain at their stations unless otherwise directed by a voice paging announcement. The evacuation of a large area or entire building is unlikely due to the localized use of hazardous materials. However, standard evacuation practices would be used if such evacuation is appropriate for a specific accident.

I	INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
İ	RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
Į	<u>-</u>	ENGINEERING CENTER (INTEC),	Page:	G4 of G25
		APPENDIX G	_	
١	INTEC Facility	SPILL PLAN		

G1.2 Radiological

A release of radioactive material could cause wide spread contamination over a large area of INTEC. This could occur as a result of a fire or explosion in a radioactive materials container. Leaks of a radioactive vapor may cause similar contaminations as particles in the vapor settle.

G1.3 Nonradiological

Nonradiological chemicals used throughout INTEC could result in a hazardous situation in which personnel might come in contact with the hazardous chemical. Much care must be given when responding to or cleaning up the spill or leak so that IRT members do not endanger their own or other lives. A planned procedure must be followed so additional emergency situations can be avoided.

G2. ACTIONS TO BE TAKEN IN RESPONSE TO A RELEASE, SPILL, OR LEAK

Certain steps need to be followed when dealing with any chemical spill or leak that is encountered, although the actual extent of the actions taken will be dictated by the specifics of the release, which would include the nature, volume, and location of the release. The following steps must be taken by operations and/or emergency response personnel in dealing with any release.

- 1. If the release involves a flammable/combustible liquid, contact the fire department (call 777) immediately.
- Assist any employees that have been exposed to the release, or have suffered an
 injury, in receiving proper first aid and/or immediate medical attention. If exposed
 to the release by direct contamination, then decontamination should be
 accomplished as applicable.
- 3. Take steps to secure the area to prevent inadvertent exposure to the release or release byproduct (vapor or gases) by other personnel. Use safety rope and/or signs or direct personnel to remain stationed in certain locations.
- 4. Contact the immediate job supervisor, the building Tenant Manager, the plant shift supervisor, the Radiation Controls (Radcon) supervisor, the INTEC environmental support supervisor, and the Environment, Safety, and Health (ES&H) manager. These notifications are important, especially for obtaining guidance to handle the incident properly.
- 5. Obtain proper personnel protective equipment to control, clean up, and dispose of the released material as directed by industrial safety, material management, and environmental assurance personnel. The type of protective clothing and other

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G5 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

equipment required will be delineated on a required hazardous work permit. If the material released is radioactive, contact a Radcon supervisor as well as industrial safety personnel. Handling of radioactive materials will require a radiation work permit. When details regarding the release are not available, a conservative approach is mandatory: air-supplied respiratory equipment and full-body protective clothing must be worn. Medical monitoring will be accomplished prior to entering a hazardous materials environment when wearing Level A or B protective clothing. The buddy system will be in place along with a minimum of two backup personnel dressed in the same level of protective gear.

- 6. Take steps to control the release. This may involve shutting certain valves, diking the area (e.g., use sandbags, berms, or spill-control pillows), and/or applying an absorbent or neutralizing compound directly to the release. It is important, when utilizing an absorbent or neutralizing compound, that an appropriate product is utilized that will not have an unwanted chemical reaction, which could produce a more hazardous situation. Industrial and INTEC environmental support personnel will specify the product to be used to absorb or neutralize the released material; if radioactive, contact a Radcon supervisor.
- 7. Conduct the clean-up, storage and/or disposal of the waste under the direction of industrial hygiene, environmental support, and, if the waste is radioactive, a Radcon supervisor. However, the treating, storing, or disposing of recovered waste, contaminated soil or surface water, or any other material resulting from a release, fire, or explosion immediately after the emergency, shall be accomplished by methods approved only by the INTEC environmental support supervisor. Ensure that incompatible wastes are not treated, stored, or disposed of in the affected areas before cleanup procedures have been completed.
- 8. Clean all emergency equipment used in the affected area and restore the equipment to its ready condition, fit for its intended use. Equipment or protective clothing that cannot be suitably cleaned and returned to service shall be replaced by clean, equivalent equipment. Obtain the assistance of Industrial Hygiene and environmental support personnel for proper disposal of the used equipment and protective clothing.
- 9. Ensure that all reporting requirements and forms are completed.

For all situations, it is recommended that conservative actions be taken that assume a worst-case situation to ensure that (a) personnel are not exposed to the chemical release or to possible byproducts of the release, (b) physical damage to the facilities is kept to a minimum, and (c) no environmental hazards are created. Additionally, in the event facility operations are shut down in response to a fire, explosion, or hazardous material release, affected process or facility equipment or

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G6 of G25
	APPENDIX G	-	
INTEC Facility	SPILL PLAN		

components should be monitored for leaks, pressure buildup, gas generation, or ruptures in valves, pipes, vessels, or other equipment.

G2.1 Remedial Actions for Leaking Process Components and Other Equipment

The remedial action plans for leaking processes (pipes, valves, tanks, etc.) at INTEC is outlined below and is broken down into three specific cases depending on the type of leak discovered.

G2.1.1 Leakage From/Without Secondary Containment

This category involves direct leakage to the environment due to failure of secondary containment or the absence thereof. In this event, the following actions will be required:

- 1. If the solution is known or can be proven to be nonhazardous, no specific controls are required. Appropriate mitigative steps will be taken to minimize the extent of the leak.
- 2. If the solution is hazardous or if its hazardous nature is unknown, the following steps will be required.
 - a. Immediately notify senior management.
 - b. Take prompt measures to minimize the amount of solution reaching the environment. These actions should be initiated immediately and shall include taking the failed tank or other equipment out of service and, if possible, transferring the contents of the leaking tank to another tank.
 - c. When the release equals or is in excess of reportable quantities, the full requirements of the plan shall be in effect. If such is the case, the release must be reported to the Warning Communications Center (6-1515), the Environmental Protection Agency (EPA) Regional Administrator, the State of Idaho, and other local authorities.

However, any leak, release, or structural defect to an interior wall embedded waste line penetration (which may affect secondary containment integrity) requires immediate notification of Regulatory Affairs. Notification of Department of Energy Idaho Operations Office (DOE-ID) must occur within 12 hours of detection for lines granted secondary equivalency.

INEEL Emergency Plan/
RCRA Contingency Plan

TECHNOLOGY AND
ENGINEERING CENTER (INTEC),
APPENDIX G

INTEC Facility

Rev. 06)

PLN-1 14-2

Revision:
Page:
G7 of G25

The line must be taken out of service within 24 hours of detection. DOE-ID must notify the State of Idaho within 24 hours of detection.

412.09

- d. If the release is less than the reportable quantities, the plan may
 be partially implemented in response to the release.
 Additionally, the spill may be required for inclusion in
 Superfund Amendments and Reauthorization Act of 1986
 (SARA) reports.
- 3. If the leak was from a failed secondary containment, the system will be repaired or otherwise operated in such a manner to ensure no environmental releases are possible prior to use of the tank or equipment. If the leak was from primary containment, without a secondary containment system, a secondary containment system will be provided prior to subsequent use.
- 4. If the leakage is later found to be nonhazardous, when it was originally conservatively assumed to be hazardous, the steps outlined above are not necessary.

G2.1.1 Leakage From Primary To Secondary Containment (High Integrity)

In this case, leakage is to a secondary containment system that meets applicable criteria of compatibility with the waste and adequate protection against the potential for leakage to the environment. Once leakage is detected, the following actions will be required:

- 1. If the solution is known or can be proven to be nonhazardous, no specific actions are necessary provided the amount of leakage, if not removed from secondary containment, will not impair the ability of the leak detection mechanism to detect future leaks.
- If the solution is or might be hazardous, the following steps will be required:
 - a. Immediately notify senior management.
 - b. Take prompt measures to minimize the amount of solution reaching the secondary containment. This could include a variety of actions such as isolation, transfer to a parallel tank, etc.

			11/05/2001 1007. 007
INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
_ ,	ENGINEERING CENTER (INTEC),	Page:	G8 of G25
	APPENDIX G	_	
INTEC Facility	SPILL PLAN		ł

- c. Evaluate the physical characteristics of the leak. Attempt to identify the source of leakage, the amount or rate of leakage, composition of the solution, etc.
- d. If the leak cannot be repaired remotely and other conditions such as high-radiation fields prohibit a direct hands-on repair effort, appropriate personnel will be convened to determine the proper course of action. As a minimum, representatives from INTEC Environmental Support, Industrial Hygiene, and the department responsible for the affected system will be notified. The type of corrective action will consider the severity of the leak and the actions necessary for repair. The evaluation will consider the leak rate, composition of the solution, radiation exposures necessary for repair, the extent of decontamination required to complete repair and other pertinent factors. Under no circumstances will the leakage be permitted to threaten the environment. The amount of leakage, if allowed to persist, must be sufficiently small that it will not prevent the leak detection mechanism from functioning. Furthermore, the leakage will be removed from the secondary containment and stored or disposed of in accordance with established procedures.
- 3. The following corrective actions will be considered for selection:
 - a. Shut down the affected system and repair the leak immediately.
 - b. Shutdown the affected system and initiate actions to prevent further leakage before reuse. Evaluate system repair during the next available maintenance turnaround.
 - c. Continue operation with additional controls to minimize the amount of leakage. Evaluate system repair during the next available maintenance turnaround.
- 4. The course of action taken will be documented and justified with approval of senior management. Any surveillance activities for previously identified leaks will evaluate any changes to the amount or type of leakage. If leakage worsens, additional corrective actions and evaluations will be made. These actions will likewise be documented and approved by senior management.
- 5. Leakage that does not enter the environment will not require formal spill reporting to the EPA or the State of Idaho but may be required

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G9 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

for inclusion in SARA reports. Proper documentation regarding all key aspects of the leak should be well organized and auditable.

However, any leak, release, or structural defect to an interior wall embedded waste line penetration (which may affect secondary containment integrity) requires immediate notification of environmental compliance. Notification of DOE-ID must occur within 12 hours of detection for lines granted secondary equivalency. The line must be taken out of service within 24 hours of detection. DOE-ID must notify the State of Idaho within 24 hours of detection.

G2.1.2 Leakage From Primary To Secondary Containment (Limited Integrity)

In this category, leakage is to a secondary containment that does not meet applicable criteria of compatibility with the waste or adequate protection against the potential for leakage to the environment. If leakage of this type is detected or suspected, the following actions will be required:

- 1. If the solution is known or can be proven to be nonhazardous, no specific actions are necessary provided the amount of leakage, if left in the secondary containment, will not impair the ability of the leak detection mechanism to detect future leaks.
- 2. If the solution is or might be hazardous, the following steps will be required:
 - a. Immediately notify senior management.
 - b. Take prompt measures to minimize the amount of solution reaching secondary containment. A variety of appropriate corrective actions could be utilized but must include taking the failed system out of service.
 - c. Ensure the solution is removed from the secondary containment before the time interval for compatibility is exceeded.
 - d. If previous corrective actions have not completely stopped the leak, or allowed removal of the leakage from secondary containment, the leak will be treated as a release to the environment and handled in accordance with applicable guidelines.

			1700/2001
INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
_ ,	ENGINEERING CENTER (INTEC),	Page:	G10 of G25
	APPENDIX G	_	
INTEC Facility	SPILL PLAN		

e. If previous corrective actions completely stopped the leak and the leaked solution was promptly removed such that no environmental release resulted, a specific evaluation will be conducted. This evaluation will be held in conjunction with the DOE-ID to determine the proper course of action. This evaluation must be completed prior to returning the system to operation.

However, any leak, release, or structural defect to an interior wall embedded waste line penetration (which may affect secondary containment integrity) requires immediate notification of environmental compliance. Notification of DOE-ID must occur within 12 hours of detection for lines granted secondary equivalency. The line must be taken out of service within 24 hours of detection. DOE-ID must notify the State of Idaho within 24 hours of detection.

				1110312001
INEEL E	mergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
	ontingency Plan	TECHNOLOGY AND	Revision:	5
	<i>U</i> ,	ENGINEERING CENTER (INTEC),	Page:	G11 of G25
		APPENDIX G		
INTEC F	acility	SPILL PLAN		

G3. SPILL PREVENTION CONTROL AND COUNTERMEASURES PLAN

INTEC Persons with SPCC Plan Responsibilities				
M. J. MacConnel Phone: 526-1167 Pager: 6960 K. L. Miller Phone: 526-9733 Pager: 5336 Med A Mod Mod Mod Mod Mod Mod Mod Mod Mod Mod	6/3/2002 Date 6·3-02 Date			
Approval				
ES&H Manager, INTEC				
C. R. Jones Phone: 526-8079 Pager: 5728 C. R. Jones Signature Signature	6-3-02 Date			
Area Director, INTEC The Spill Prevention, Control, Countermeasures Plan will be imp	elemented as herein described:			
R. R. Chase Phone: 526-0018 Pager: 5669	C/3/02 Date			
Certification I hereby certify that I have examined the facility, and being familiar with the provisions of 40 CFR 112, attest that this plan has been prepared in accordance with good engineering practices.				
CHINTON O. KINGS	FORD			

Printed Name of Registered Professional Engineer	_
Coi de Kingdan Claster Harris	X
Signature of Registered Processional Engineer	•
0.03.03.03.0	
(2:03:02 2104 DAHD DAHD	
Date Registration Number State Vo. Kind	

(11/05/2001 - Rev. 06)	4	12.09	
	(1	1/05/2001	- Rev. 06

			(11105: E001 1te1: 00)
INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
_	ENGINEERING CENTER (INTEC),	Page:	G12 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

G3.1 General Information

G3.1.1 Regulatory Background

This Spill Prevention, Control, and Countermeasures (SPCC) Plan has been prepared in accordance with 40 Code of Federal Regulations (CFR) 112, Oil Pollution Prevention. It addresses both aboveground and underground oil storage containers, including electrical transformers with 660 gal or more of oil, at the INEEL INTEC.

In accordance with 40 CFR 112.1(a.), the purpose of this SPCC plan is to establish requirements "to prevent the discharge of oil, through a spill event, from nontransportation-related onshore and offshore facilities into or upon the navigable waters of the United States or adjoining shorelines." A spill event is defined as a release of enough oil to navigable waters of the United States to violate applicable water quality standards, to cause a film or sheen on or discoloration of the water or adjoining shorelines, or to cause a sludge or emulsion to be deposited beneath the surface of the water or on adjoining shorelines [40 CFR 110.5 (a) and (b)].

G3.1.2 Facility Description

1 Name of facility

	•	Center (INTEC) (see Figure G1).
2	Type of facility	Receive and store spent nuclear fuel and prepare it for final disposition. Dispose of CERCLA low-level and/or mixed low-level radioactive waste.
3	Location of facility	Approximately 2 mi north of the Central Facilities Area.
4	Name of owner	U.S. Department of Energy.
5	Address of owner	U.S. Department of Energy Idaho Operations Office 785 Department of Energy Place Idaho Falls, ID. 83401-1562

Idaho Nuclear Technology and Engineering

			412.09 (11/05/2001 – Rev. 06)
INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G13 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		




Figure G1. Location of the INTEC within INEEL boundaries.

	INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
	RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	-	ENGINEERING CENTER (INTEC),	Page:	G14 of G25
		APPENDIX G		
i	INTEC Facility	SPILL PLAN		

The INTEC is one of the principal facilities at the United States Department of Energy's (DOE) INEEL, located approximately 50 mi west of Idaho Falls and north of State Highway 20 (see Figures G1 and G2). INTEC began operation in 1953. INTEC's original mission was to receive, store, and reprocess spent nuclear fuel from test and research reactors in the United States and foreign countries, including the U.S. Navy's ship propulsion reactors. In 1992, INTEC's mission was changed to receive and store spent nuclear fuel and prepare it for final disposition. Construction of the ICDF complex began in 2001. The ICDF complex is designed to function as an INEEL site wide disposal facility to accommodate receipt, staging, storage, treatment, and disposal of soil debris and liquid waste generated from CERCLA activities.

The INTEC is located on relatively flat terrain (less than 1% grade with localized depressions) made up of poorly sorted gravel and gravely, coarse sand with abundant well-rounded small cobbles and traces of silt and clay, most of which has been disturbed and replaced with gravel. The gravel acts as a natural velocity dissipation control for surface flows. The Big Lost River is an intermittent stream that terminates into a local playa. In wet years, it can flow year round. In dry years, it may not flow at all in the vicinity of INTEC.

G3.2 Spill Events

The INTEC has never discharged more than 1,000 gal of oil into or upon navigable waters of the U.S. in a single spill event or discharged oil in harmful quantities as defined in 40 CFR 110 into navigable waters of the U.S.

G3.3 Oil Storage Capacity

Table G3.3.1 lists the aboveground storage tanks (ASTs) and Table G3.3.2 the underground storage tanks (USTs) at INTEC that are subject to SPCC regulations.

Table G3.3.3 lists those transformers at INTEC that are subject to SPCC regulations. Based on a teleconference with EPA Region X personnel, only electrical equipment with a capacity of 660 gal or greater needs to be addressed in an SPCC plan.

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G15 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

 Table G3.3.1. Aboveground storage tanks.

Location	Tank	Content	Gallons	Status	Comments
E of CPP-701	VES-UTI-681	#2 fuel oil	244,000	Active	Boiler fuel
E of CPP-701	VES-UTI-681 VES-UTI-682	#2 fuel oil	57,000	Active	Boiler fuel
	VES-U11-082 VES-KRS-100	_	ŕ	Active	
S of CPP-1682	VES-KRS-100	kerosene	10,000	Active	Replaced VES-WDS-100 and -101
S of CPP-1682	VES-KRS-101	kerosene	10,000	Active	
S of CPP-702	VES-WDS-100	kerosene	20,000	Active	Storing fuel for CFA buses
S of CPP-702	VES-WDS-101	kerosene	20,000	Active	Storing fuel for CFA buses
N of CPP-644	VES-PHE -102	diesel	3,000	Active	CPP-644 standby generator
N of CPP-775	VES-CFG-6011	#2 fuel oil	1,500	Active	CFSGF, boilers
CPP-687	VES-CFG-6022	#2 diesel	275	Active	GEN-CFG-001 standby generator day tank
CPP-1642	VES-UTI-113	diesel	560	Active	Diesel, firewater pump fuel
CPP-1643	VES-UTI-114	diesel	560	Active	Diesel, firewater pump fuel
CPP-614	VES-UTI-620	diesel	300	Active	Diesel, raw water pump fuel
CPP-637	VES-YDC-105	kerosene	500	Active	Pilot plant experiments
CPP-1749	VES-YDA-107	diesel	165	Active	Diesel, water pump fuel
CPP-644	VES-UTI-656	diesel	50	Active	CPP-644 standby generator day tank
CPP-616	VES-UTI-168	diesel	180	Active	Standby plant air compressor
CPP-1684	VES-WCS-103	#2 diesel	240	Active	Emergency generator day tank
		Total:	367,815		
		· · · · · · · · · · · · · · · · · · ·			

			137007000
INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G16 of G25
i ·	APPENDIX G		{
INTEC Facility	SPILL PLAN		

Table G3.3.2. Underground storage tanks.

Location	Tank	Content	Gallons	Status	Comments
SE cor. of CPP-659	VES-NCE-140-1	diesel	5,000	Inactive	Standby generator
SE cor. of CPP-659	VES-NCE-140-2	diesel	5,000	Inactive	Standby generator
S of CPP-1684	VES-WCS-106	#2 diescl	10,000	Active	Standby generator
S of CPP-660	VES-SAA-152	diesel	2,500	Active	Gas Boy pumps
S of CPP-660	VES-SAA-153	gasoline	5,000	Active	Gas Boy pumps
		Total:	17,500		

Table G3.3.3. Transformers 660 gallons or greater.

Location	Transformer	Content	Gallons	Status	Comments
B21-620 substation	6-073	oil	6,400	Active	No PCBs
B21-620 substation	6-074	oil	6,400	Active	No PCBs
		Total:	12,800		

G3.4 Oil Flow Direction and Facility Drainage

Figure G2 shows the surface drainage flows at INTEC. The nearest waters of the U.S. is the Big Lost River (BLR), which is outside the northwest corner of the facility.

Except under extreme conditions, all INTEC drainage is retained at the facility. The facility is currently surrounded by a stormwater drainage system with discharges to an abandoned gravel pit located on the East Side. The pit can contain approximately 400,000 ft³ of liquid. There is no record of the pit ever filling to the point of overflow. Water that accumulates in the pit either evaporates or infiltrates. The pit is located approximately 2,000 ft from the Big Lost River and is separated from the river by a large vegetated natural basin and a large dike running along the riverbank. On the northeast side of the basin, culverts cross under an elevated railroad dike and enter another natural basin. The dike along the river stops in this basin and, therefore, there is a remote potential of a discharge from this basin to the Big Lost River from this basin during extreme conditions.

		* 1	412.09 (11.05/2001 - Rev. 96)
INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR TECHNOLOGY AND	Identifier:	PLN-114-2
RCRA Contingency Plan	ENGINEERING CENTER (INTEC),	Revision:	5
INTEC Facility	APPENDIX G, SPILL PLAN	Page:	G17 of G25




Figure G2. INTEC facility map.

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G18 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

However, excluding the manmade features (i.e. pit, dike, railroad tracks, ditches, etc.), there may be a potential for oil to reach the Big Lost River in the event of a spill if it coincided with a worst-case runoff event.

Aboveground CPP-701 storage tanks VES-UTI-681 and VES-UTI-682 contain the bulk of the total oil stored at INTEC and are the greatest potential source for a major oil spill. The storm water drainage system at INTEC, including the area around the CPP-701 fuel oil storage tanks, is currently being upgraded. The upgrade consists of lining the drainage ditches in a large area of INTEC with concrete and constructing a 1.26 million ft³ evaporation pond double lined with a geotextile (polypropylene) liner. The pond is designed to store a 25-year worst-case snowmelt event and is equipped with two gated outlet culverts that are placed at the upper elevation of the pond. The gates will allow draw down of the pond level as needed and also could be used to prevent discharge from the pond in the event of an oil release to the pond. This pond is also located on the East Side of the facility next to the existing pit currently being used. Drainage from the pond outlet will also follow the same flow path to the Big Lost River as previously described for the existing drainage system. Construction for this drainage upgrade is underway, however, due to funding uncertainties, a completion date for this project is uncertain.

The drainage system at the Coal-Fired Steam Generation Facility (currently not in operation), which contains tanks VES-CFG-6011 and -6022, consists of a trench surrounding the north area of the facility and part of the INTEC drainage system on the west and south sides of the facility. The trench around the north area is designed to contain a 10-year, 24-hour rainfall event.

G3.5 Oil Spill Containment and Diversionary Structures and Equipment

Containment and diversionary structures are provided to prevent discharged oil from reaching a navigable water course.

All ASTs, with the exception of VES-UTI-168, have some form of secondary containment. Tank VES-UTI-168 is located east of building CPP-616 and does not have secondary containment. However it does have a spill pan to collect leaks and small spills. Tanks VES-UTI-102, VES-CFG-6011, VES-KRS-100, and VES-KRS-101 have leak detection and associated alarm systems. All other AST secondary containments are checked once a shift for leaks in accordance with Conduct of Operations Procedure, Chapter II, *Shift Routines and Operating Practices* (MCP-2974).

The CPP-701 aboveground storage tanks (VES-UTI-681 and -682) are contained within a 10-ft high earthen berm that has sufficient capacity to contain the contents of the largest single tank plus sufficient freeboard to allow for

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G19 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

precipitation, or the entire contents of both tanks should they rupture simultaneously.

Tanks VES-WDS-100 and -101 are surrounded by an earthen berm designed to contain the contents of one tank. These tanks are 20,000 gal capacity each, but presently contain approximately 3,900 gal of kerosene each. These tanks are currently out of service and there are no plans for future use. Tanks VES-KRS-100 and -101 are carbon steel tanks built within a concrete vault, constructed in 1996. The vault can hold 110% of one tank. The vault also has local and remote leak detection alarms to indicate when a leak occurs.

Tanks VES-PHE-102 and VES-CFG-6011 are constructed of single-wall carbon steel and seated within individual concrete vaults designed to hold 110% of tank contents. VES-PHE- 102 provides fuel for the standby generator located in CPP-644. VES-CFG-6011 provides fuel for the standby generator at the Coal Fired Steam Generation Facility. VES-UTI-620, 300 gal, is constructed of steel and is situated in a concrete vault. VES-UTI-620 is located inside CPP-614. VES-UTI-113 and -114, both 560 gal, are also steel tanks situated above concrete vaults. VES-UTI-113 is located inside CPP-1642 and VES-UTI-114 is located inside CPP-1643. VES-YDC-105 is steel tank enclosed in concrete (Convault design) with interstitial monitoring. VES-YDA-107, 165 gal, is constructed of steel and is surrounded by a curbed area. The curbed area will hold 215 gal. VES-YDA-107 is located inside CPP-1749.

VES-UTI-656 is a 50 gal steel tank located inside CPP-644, VES-WCS-103 is a 240 gal steel tank located inside CPP-1684, and VES-CFG-6022 is a 275 gal steel tank located inside CPP-687. These are day tanks for associated standby generators. The buildings act as secondary containment for these tanks.

The diesel powered standby plant air compressor is located east of building CPP-616. This compressor has a 180 gal diesel fuel tank (VES-UTI-168), which is an integral part of the compressor. A small spill would be contained in the drip pan; however, larger spills could reach the environment.

All USTs have double containment and are equipped with interstitial leak detection in the interstitial area. If a leak occurs, it would be contained by the secondary liner. Repairs would include removal of the tank to either repair the primary liner or replace the tank.

Underground storage tanks VES-NCE-140-1 and -2 once contained diesel fuel for NWCF standby generators. These tanks are double-wall fiberglass-reinforced plastic (FRP) and were installed in 1995 to comply with 40 CFR 280 UST regulation upgrades. Each tank has a capacity of 5,000 gal with interstitial leak detection. These tanks are now inactive and the fuel has been transferred to a

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
_ ,	ENGINEERING CENTER (INTEC),	Page:	G20 of G25
	APPENDIX G	_	
INTEC Facility	SPILL PLAN		

replacement tank, VES-WCS-106. This UST is a 10,000 gal, double wall, fiberglass tank with interstitial monitoring and float switch monitoring for overfill protection. This tank will now provide fuel for the three standby generators located in CPP-1684.

Tank VES-SAA-152 is a 2,500 gal FRP double contained tank. It contains diesel for vehicle refueling. It was installed in 1995 as part of the INTEC tank upgrade project to meet 40 CFR 280 UST requirements. The tank has interstitial monitoring that alarms when any leakage is detected. Tank VES-SAA-153 is a 5,000 gal FRP double contained tank. It contains gasoline fuel for vehicle refueling. It was installed the same time as VES-SAA-152 in 1995 to comply with the UST regulations. It also has interstitial monitoring to detect any leaks from the primary containment tank with local leak detection alarm.

The two electrical transformers of concern listed in Table G3.3.3 are located in substation yards with deep gravel bases, which can hold the contents of the largest single transformers. Oil in these transformers contain no PCBs.

INTEC is completely surrounded by a storm water drainage system that does not discharge to waters of the United States. In the unlikely event that oil entered this drainage system, it would be contained within the system.

G3.6 Miscellaneous Control Measures

Catch pans are placed under the fill connections to prevent spills when oil is unloaded from the delivery trucks (INTEC TPR-P9.3-D8). USTs have spill control cabinets inside the building of the equipment they feed. The Gas Boy dispensing pumps at CPP-660, which feed from UST VES-SAA-152 and -153, also have spill control equipment in case of a spill.

G3.7 Fail-Safe Engineering

The material and construction for all tanks at INTEC are compatible with the materials stored. All tanks levels can be monitored through manual probing, external direct vision fuel level indicators, and/or electronic liquid level sensing devices. The type of containment for each tank has been described previously as well as the response to any leak detection.

Tanks VES-KRS-100 and VES-KRS-101 also have high-level alarms for protection against overflow. These alarms also alert Operations personnel of piping or tank failure because they are also triggered when low-level conditions are present. All fill pipes and ports are protected from traffic by either guards or distance.

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G21 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		,

All utility areas are inspected each shift by Utility Operations as required by Conduct of Operations procedures.

All newly installed buried pipelines have protective coatings or cathodic protection, or are sleeved for secondary containment.

Traffic at the INTEC facility is limited because of the high degree of security at the facility. No overhead piping systems are outside of buildings exposed to traffic and those systems located inside buildings are designed with sufficient clearance that there is no risk of collision with utility or transport vehicles.

Gasoline and diesel Gas Boy dispensers have high alarms on their storage tanks, which activate at 95% full.

The fuel delivery trucks have pressure sensitive cut-off nozzles, which shut off the fuel flow when the tank is full.

INTEC TPR-P9.3-D8 provides instructions for operating the fuel oil and diesel fuel storage and supply system. This procedure includes steps for receiving and unloading fuel oil, diesel fuel, and emergency actions in the event of a leak, spill, or tank overfill.

G3.8 Wastewater Effluent

The wastewater system at INTEC is sufficiently tight that it is not plausible that oil could enter the system.

G3.9 Correction Of Oil Leaks

INTEC has a work control maintenance program to ensure that oil leaks are corrected promptly upon discovery. Work order control is accomplished by STD-101, Integrated Work Control Process.

G3.10 Portable/Temporary Tanks

Portable/temporary oil storage tanks may be brought onto the facility and covered under this SPCC plan if the owner/operator of the tank submits and obtains approval of form 435.33 from the facility's responsible SPCC person (see page G11). The approved form is to be maintained at the facility with the facility SPCC plan.

G3.11 Spill Response

Should a spill occur, the facility needs to follow the *INEEL Emergency Plan/RCRA Contingency Plan*, which describes measures to be taken to prevent,

(11/05/2001 - Rev. 06) PLN-114-2

412.09

ADDENDUM 2, IDAHO NUCLEAR | Identifier: INEEL Emergency Plan/ RCRA Contingency Plan **TECHNOLOGY AND** Revision: Page: G22 of G25 ENGINEERING CENTER (INTEC). APPENDIX G SPILL PLAN INTEC Facility

> control, and clean up any chemical or oil spills at the facility. The emergency action manager needs to respond also to requirements in MCP-190, Occurrence Reporting and MCP-3480, Environmental Instructions for Facilities, Processes, Materials and Equipment. One of the primary goals of the response action is to prevent discharged oil from reaching waters of the U.S. and causing other damage or injury. Copies of the INEEL Emergency Plan/RCRA Contingency Plan are maintained and are to be used in conjunction with this SPCC Plan.

The general procedure for oil spill response is as follows:

- 1. Control the spill at the source.
- 2. Identify the area of the spill.
- 3. Secure the area of the spill.
- 4. Ouantify the spilled material using one or more of the following methods:
 - Subtract volume in the tank after the spill from volume before the a. spill.
 - b. Ouantify amount of spilled material recovered.
 - Measure or estimate dimensions of spilled area. C.
 - d. Any other method appropriate for quantifying the spill.
- 5. Report spill to the plant shift supervisor (PSS). This report should include the following spill information:
 - Time
 - Location
 - Material
 - Quantity
 - Source
 - Cause
 - Release area.

The INEEL Spill Notification Team (SNT) at Pager number 6400 must be contacted promptly. It is the plant shift supervisor's responsibility to ensure that the SNT is contacted, and to assist them in making the correct notifications. Depending on the source, volume, and location of the spill, notifying several persons and agencies may be necessary.

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G23 of G25
	APPENDIX G]	
INTEC Facility	SPILL PLAN		

None of the containment areas (i.e., berms or buildings) has valves that enable drainage from the containment; therefore, personnel respond to a spill by either using sorbent materials to absorb the spillage or pumping the spillage depending on circumstances. Contaminated materials, including soil, resulting from the spill are disposed in accordance with applicable state and federal regulations.

G3.12 Tank Truck Loading and Unloading

Oil loading and unloading operations from tanker trucks to ASTs or USTs do not occur in contained areas. Most of the refueling areas are on gravel, dirt, or paved surfaces. Levels in tanks are checked before filling begins. Truck drivers are to monitor the vehicle continually while off-loading to ensure that no leaks are coming from valves, fuel transfer lines, etc. Tanks are not to be filled beyond the 90% level to avoid overfilling and ensure adequate air space for fuel expansion.

As part of the drainage upgrade described in Section G3.4 of this plan, the unloading rack area (including hose port fuel pump house, and truck parking area) for CPP-701 has been paved and sloped to provide immediate drainage to an adjacent concrete ditch. The current drainage system and the future upgrades will provide a quick drainage system and containment for tanker truck unloading operations in this area.

G3.13 Inspection and Records

All utility areas and the Coal Fired Steam Generation Facility with ASTs are inspected each shift by Utility Operations as required by Conduct of Operations procedures. The inspection reports are maintained in the Utility Operations records file for a minimum of 3 years.

The other fuel oil ASTs (VES-KRS-100 and -101, VES-WDS-100 and -101, and VES-YDA-107) are inspected each shift by Waste Operations personnel as required by Conduct of Operations. The inspection log is maintained by the Waste Operations department and retained for a minimum of 3 years.

VES-YDC-105 is inspected for chemical usage at a minimum of once every 3 weeks in accordance with MCP-2873, INEEL Chemical Management System (ICMS). ICMS is a chemical inventory used to track chemical usage and also types and locations of chemical containers.

The USTs are equipped with computer systems that monitor various functions. Computer program records are available if needed by contacting the tank owners. Because all the oil carrying USTs at INTEC are fiberglass with double walls, and have internal leak detection, no regular pressure testing for tightness is required.

INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G24 of G25
	APPENDIX G		
INTEC Facility	SPILL PLAN		

G3.14 Security

DOE has established physical control procedures and equipment to control access to the INTEC. The INTEC is fully fenced and all entrance gates are locked or guarded at all times. The system follows DOE-ID directives and orders on access control. DOE also operates a personnel clearance program to ensure that all employees are evaluated and cleared. The risk of potential sabotage or planned destruction of a critical operating system is therefore minimal.

In addition to the physical security at INTEC, there are Operations administrative procedures in place to reduce the potential for tank leakage to navigable waters of the United States. Included in these measures are locked and tagged valves, blind flanges when in standby or nonoperational status, authorized access only to pumping facilities, and localized lighting around tank systems to more readily detect spills or acts of vandalism.

G3.15 Personnel, Training, and Spill Prevention Procedures

The Plant Shift Supervisor (PSS) coordinates the daily activities at INTEC and also acts as the emergency action manager during emergency response situations. The PSS can be reached at 6-3100.

Supervisors are responsible to properly instruct their personnel in the operation and maintenance of equipment to prevent discharges of oil. Personnel must maintain an adequate understanding of this SPCC plan, the INEEL Emergency Plan/RCRA Contingency Plan (Addendum 2, Idaho Nuclear Technology and Engineering Center), and be familiar with applicable the pollution control laws, rules and regulations associated with these plans. Spill prevention briefings are to be given periodically to personnel to describe and discuss known spill events or failures, malfunctioning components, and recently developed precautionary measures.

Designated personnel who are accountable for oil spill prevention at INTEC can be found on page G11.

G3.16 Other Regulations

ASTs are regulated primarily by the Occupational Safety and Health Administration, the National Fire Protection Association, and SARA, while USTs are regulated primarily by the EPA. Tanks used for storing heating oil for consumptive use on the premises where stored are exempt from the requirements of 40 CFR 280. Tanker trucks used for refueling are regulated and in compliance with U.S. Department of Transportation regulations. Petroleum product storage and transfer is regulated by the Storm Water Multi-Sector General Permit for

			(11111312001 11011 00)
INEEL Emergency Plan/	ADDENDUM 2, IDAHO NUCLEAR	Identifier:	PLN-114-2
RCRA Contingency Plan	TECHNOLOGY AND	Revision:	5
	ENGINEERING CENTER (INTEC),	Page:	G25 of G25
	APPENDIX G	_	
INTEC Facility	SPILL PLAN		

Industrial Activities (40 CFR 122), which is part of the National Pollutant Discharge Elimination System of the Clean Water Act.

Appendix L Procedures Relevant to RA Activities

Appendix L

Procedures Relevant to RA Activities

INEEL, GDE-7003, "Levels of Analytical Method Data Validation," current issue.

INEEL, Manual 15B, Radiation Protection Procedures, current issue.

INEEL, Manual 18, Closure Management, current issue.

INEEL, MCP-62, "Waste Generator Services—Low-Level Waste Management," current revision.

INEEL, MCP-63, "Waste Generator Services—Conditional Industrial Waste Management," current revision.

INEEL, MCP-69, "Waste Generator Services—Hazardous Waste Management," current revision.

INEEL, MCP-70, "Waste Generator Services—Mixed Low-Level Waste Management," current revision.

INEEL, MCP-83, "Characterization of Low-Level Radioactive Wastes for Disposal at the INEEL," current revision.

INEEL, MCP-121, "Areas Containing Radioactive Materials," current revision.

INEEL, MCP-451, "Generator Treatment Plans," current revision.

INEEL, MCP-598, "Corrective Action System," current issue.

INEEL, MCP-1141, "Waste Stream Approval Process," current revision.

INEEL, MCP-2391, "Calibration Program," current issue.

INEEL, MCP-2725, "Field Work at the INEEL," current issue.

INEEL, MCP-2811, "Design and Engineering Change Control," current issue.

INEEL, MCP-3002, "Managing Disturbed Soils," current issue.

INEEL, MCP-3003, "Performing Pre-Job Briefings and Post-Job Reviews," current issue.

INEEL, MCP-3448, "Reporting or Disturbance of Suspected Inactive Waste Sites," current issue.

INEEL, MCP-3472, "Identification and Characterization of Environmentally Regulated Waste," current revision.

INEEL, MCP-3475, "Temporary Storage of CERCLA-Generated Waste at the INEEL," current revision.

INEEL, MCP-3480, "Environmental Instructions for Facilities, Processes, Materials, and Equipment," current revision.

INEEL, MCP-3562, "Hazard Identification, Analysis and Control of Operational Activities," current issue.

INEEL, MCP-3653, "Well Construction, Modifications, Compliance, and Management," current issue.

INEEL, PLN-123, "Materials Control and Accountability Plan for Safeguards," current revision.

INEEL, PRD-25, "Activity Level Hazard Identification, Analysis, and Control," current issue.

INEEL, **PRD-5030**, **a**, "Environmental Requierments for Facilities, Processes, Materials, and Equipment," current issue.

INEEL, STD-101, "Integrated Work Control Process," current issue.

INEEL, TPR-4910, "Logbook Practices for ER and D&D&D Projects," current issue.

INEEL, TPR-6565, "Core Sampling," current revision.

INEEL, TPR-6566, "Measuring Groundwater Levels," current issue.

INEEL, TPR-6572, "Installing Lysimeters and Sampling Soil Pore Water," current issue.

INEEL, TPR-6574, "Decontaminating Heavy Equipment, in the Field," current issue.

INEEL, TPR-6575, "Decontaminating Sample Equipment in the Field," current issue.

Appendix M

INEEL Storm Water Pollution Prevention Plan for Construction Activities – Generic Plan

DOE/ID-10425(98) Revision 2

[The document that is the subject of this appendix was provided as an attachment to the original deliverable.]

To view this Appendix, please see specific "Stand Alone" document number

(**NOTE:** The document number referenced is a "Generic Plan Template" used to build the file, it is not a document)

450.15 03/15/2000 Rev. 02

Storm Water Pollution Prevention Plan For Construction Activities (SWPPP-CA) SHORT FORM PROJECT

PROJECT TO	TLE:	WAG 3 OU 3-1	3 Group 5 Snake River Plain Aquifer		
Facility or Loc	ation:	NEEL		Environmental Checklist No.: INEL-00-0	22 Rev. 1
Project Descr	iption:				
sampling oper and Environm evaluate the name the model pre- located betwee River Plain Ad- agency (DOE,	rations in ental Lat nodel-pre- dictions to en the H puffer und EPA, ar	and around the coratory (INEE edicted hot spot for contaminan and I basalt fix der and in the value of Idah	e Idaho Nuclear Technology and Engin L). The purpose of this project is to gui t above, below, and within the "Al" inter t of concern (COC) concentrations in 20 bow beds. The project will also collect dicinity of the INTEC facility. Field samp	d Liability Act (CERCLA) action will conduct leering Center (INTEC) at the Idaho National de the collection and analysis of groundwate bed to check the WAG-3 RI/FS model accurate post and beyond. "HI" is the nomenciature for ata from wells over a 20-year period to evaluate oling activities will be conducted in accordanitioning System and Installation Plan for Operations.	al Engineering er information to racy and update or the interbed uate the Snake ce with the
Specific activit	ies that p	ootentially invo	ve disturbing seil include:		
			he vicinity of the model-predicted hot sp alls will be located as shown on the atta	oot south of INTEC to evaluate the existence ched map.	e and magnitude
			amination pad for field cleaning of well area as shown on the attached map.	drilling and support equipment. The decont	amination pad
Project Constr	uction Da	ate/Duration:	July 2002/Finish well drilling activities \$	September 30, 2002	
Area of Site to	be distu	rbed: About 1	/3 acre per installation (up to 5 wells/bo	reholes) will be mowed, about 2 acres total	
Standard requi	rements				
\boxtimes	Spill prevention measures and prompt deanup of any liquid or dry material spills.				
Minimize offsite tracking of sediments from vehicles.					
⊠	Minimize area of disturbance and preserve vegetation.				
\boxtimes	Good Housekeeping procedures, including:				
	Ø	Proper	and orderly storage of chemicals, pesti	cides, fertilizers, fuel, and other hazardous r	naterials.
	☒	Proper	and regular disposal of sanitary, constr	uction, and hazardous wastes.	
\boxtimes	Fugitive dust control measures.				
⊠	Perform inspection prior to project close-out,				
	Attach a site map which indicates drainage patterns, discharge locations, potential pollution sources (equipment and material storage areas including soil piles), areas of soil disturbance, and stabilization practices.				pment and
_					

Final Stabilization: (Identify soil stabilization measures and describe scheduling. Identify the entitles responsible for implementation and maintenance.)

Mowed areas will be evaluated for reseeding but should not require it because roots are likely to survive. Reseeding will be performed if recommended by a Plant Ecologist.

450.15 03/15/2000 Rev. 02

Storm Water Pollution Prevention Plan For Construction Activities (SWPPP-CA) SHORT FORM PROJECT

Allowable Non-Storm Water Discharge: (Identify type of discharge and describe pollution prevention measures.)

There will be some development water, some water from decontamination activities, and limited amounts of purge water. All water will be contained and managed according to the project Waste Management Plan.

I have evaluated and identified controls adequate to meet the requirements of the !NEEL Storm Water Pollution Prevention Plan for Construction Activities.

Project Manager

Project Manager

Fig. 1/07

Date

1 am in agreement with the provisions set forth in this plan.

INEEL SWPPP Coordinator:

4-30-02

Worksheet must be appended to the Generic Plan or Facility SWPPP-CA.